

S14-3



Commercial Vehicle Inspection Report

Decal Number: GN66016
Decal Expiry Date: 2026-Nov-30
Inspection Number: 21793500

Inspection Result:

PASS

FACILITY: MODERN DIESEL TRUCK REPAIR LTD. / S15400
INSPECTOR: KAMBOJ, RAJDEEP / 300155
WORK ORDER #:

INSPECTION TYPE: Complete
INSPECTION CLASS: Class 3 - Trailer and Semi-Trailer
INSPECTION REASON: Semi-annual

INSPECTION START: 2026-May-29 03:20 PM PDT
INSPECTION COMPLETE: 2026-May-29 05:40 PM PDT

VEHICLE JUR: British Columbia
PLATE #: 42035L
LICENCED GVW(kg): 0
VEHICLE YEAR: 2020
MAKE: LANGFAB
MODEL:

REGI: 13143945
UNIT/FLEET#: 122B
BODY STYLE: Dump Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 2L9PPA6C3LS014103
OWNER/LESSEE NAME: E2L CONSTRUCTION LTD.,
ADDRESS: 234-2035 GLENAIRE DR
North Vancouver, British Columbia
V7P1Y2, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) 1XL LEFT SLACK ADJUSTER REPLACED & 1XL LEFT BRAKE + DRUM REPLACED
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed with Caution 1XL TIRES SCUFF MARKS
Section 9B - Wheels	Repaired (same day) 1XL LEFT WHEEL SEAL & HUB CAP REPLACED
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	34	36
2	Clamp	30	Automatic	38	38
3	Clamp	30	Automatic	41	38

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
9.5	8.7	7.9	8.7	
9.5	9.5	8.7	10.3	
10.3	7.9	11.9	11.1	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	25	60
2	55	60
3	65	70

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	21	17
Lining (Shoe)	17	17
Lining (Shoe)	16	15

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	419.10	420.67
Drum	420.57	420.67
Drum	421.01	421.13

Comment:

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Road Tester:

Inspector: KAMBOJ, RAJDEEP

Signature:

This Inspection Report was submitted to CVSE on 2026-May-30 06:44 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

5/30/2026 6:44:31 PM PDT