



Commercial Vehicle Inspection Report

Decal Number: GM09895
Decal Expiry Date: 2026-Nov-30
Inspection Number: 21761808

Inspection Result:
PASS

FACILITY: PRO-CUT INDUSTRIES LTD / S20273
INSPECTOR: ISAAC, MORGAN / 300811
WORK ORDER #:
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual
INSP. START: 2026-Apr-30 08:56 AM -08
INSP. COMPLETE: 2026-May-06 07:50 AM -08
VEHICLE JUR: British Columbia
PLATE #: 42916P
LICENCED GVW(kg): 63500
VEHICLE YEAR: 2015
MAKE: PETERBILT
MODEL:
REGI: 11002526
UNIT/FLEET#: 11002526
BODY STYLE: Truck Tractor
ODOMETER: 1727061 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 1XPWD49X4FD254896
OWNER/LESSEE NAME: SHA-DAINE HOLDINGS, LTD
ADDRESS: 212 COLLIS ST
Creston, British Columbia
V0B1G6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) replaced #2L axle bolts
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed with Caution replaced #2R brake shoes, drum, #2L piggyback, #3R slack and brake pot, #2L brake shoes caution
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) replaced #1R king pin
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) replaced LF turn signal bulb, repaired tail light wiring, replaced license plate light, replaced mirror turn signals
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Automatic	31.8	31.8	11			11	✓
2	Clamp	30L	Automatic	44.5	47.6	10	10	9	11	
3	Clamp	30L	Automatic	44.5	76.2	10	10	9	9	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	80	65	Lining (Shoe)	14.3	14.3	Drum		
2	100	120	Lining (Shoe)	12.7	12.7	Drum		
3	35	75	Lining (Shoe)	17.5	15.9	Drum		
Comment:			Comment:		Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.			

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: ISAAC, MORGAN

Signature: morganisaac

This Inspection Report was submitted to CVSE on 2026-May-06 07:53 AM -08

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CV/SE0014

5/6/2026 7:53:51 AM -08