



Commercial Vehicle Inspection Report

Decal Number: GN84965
Decal Expiry Date: 2027-Apr-30
Inspection Number: 21956761

Inspection Result:
PASS

FACILITY: PETERBILT PACIFIC INC. / S20198 INSP. TYPE: Complete INSP. START: 2026-Oct-16 10:15 AM MST
INSPECTOR: Schroeder, Lawrence Francis / 112097 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2026-Oct-16 01:10 PM MST
WORK ORDER #: CN6906 INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 10651371 VIN: 2K9DP33599L052164
PLATE #: 74290U UNIT/FLEET#: BTRAIN LEA OWNER/LESSEE NAME: SHA-DAINE, HOLDINGS LTD
LICENCED GVW(kg): 999999 BODY STYLE: Dump Trailer ADDRESS: 212 COLLIS ST
VEHICLE YEAR: 2009 ODOMETER: Creston, British Columbia
MAKE: K-LINE HUB ODOMETER: V0B1G6, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

C16-2

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACED BRAKE LINING #3 LEFT
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) REPAIRED CRACKS IN DUMP BOX AND CROSSMEMBERS
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axes	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	39	39	9	5	15	15	
2	Clamp	30	Automatic	40	41	6	8	10	8	
3	Clamp	30	Automatic	39	39	8	6	5	4	

Comment:

Comment: TIRE TREADS GETTING LOW ON MOST TIRES BUT ALL STILL IN SPEC. WILL LET CUSTOMER KNOW

Air Brake Camshaft Rotation (degrees)

Axes	Left	Right	Brake Lining/Pad (mm)	Left	Right	Rotor Thickness or Drum Inside Diameter (mm)	Left	Right
1	45	45	Lining (Shoe)	18	18	Drum		
2	60	45	Lining (Shoe)	18	18	Drum		
3	30	60	Lining (Shoe)	21	15	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? Yes Road Test Date: Before Inspection Road Tester: LAWRENCE SCHROEDER
Inspector: Schroeder, Lawrence Francis Signature: *Lawrence Schroeder*

This Inspection Report was submitted to CVSE on 2026-Oct-16 01:15 PM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

10/16/2026 1:15:06 PM MST