



Commercial Vehicle Inspection Report

Decal Number: GN59663
Decal Expiry Date: 2027-Jan-31
Inspection Number: 21833507

Inspection Result:
PASS

FACILITY: Walkers Repair Centre / S20307 INSP. TYPE: Complete INSP. START: 2026-Jul-02 11:32 AM MDT
INSPECTOR: SCHAGER, ALBIN CARL / 106733 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more INSP. COMPLETE: 2026-Jul-02 01:32 PM MDT
WORK ORDER #: INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 13110981 VIN: 5KJJBHD1XKLKU5845
PLATE #: XY7188 UNIT/FLEET#: 310 OWNER/LESSEE NAME: Columbia, Valley Freight LTD
LICENCED GVW(kg): 46500 BODY STYLE: Truck Tractor ADDRESS: 226 Westridge DR
VEHICLE YEAR: 2019 ODOMETER: 1007136 KM Invermere, British Columbia
MAKE: WESTERN ST HUB ODOMETER: V0A1K4, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed with Caution #2 axel air bags weathered not leaking
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	30	31
2	Clamp	30L	Automatic	40	36
3	Clamp	30L	Automatic	36	30

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
8			6	✓
14	21	17	17	
12	12	12	12	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	30	30
2	45	45
3	45	45

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	21	21
Lining (Shoe)	18	18
Lining (Shoe)	18	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: SCHAGER, ALBIN CARL Signature:

This Inspection Report was submitted to CVSE on 2026-Jul-02 01:33 PM MDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVF at the Commercial Vehicle Safety Enforcement.

CVSE0014

7/2/2026 1:33:54 PM MDT