



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GN54049
Decal Expiry Date: 2026-Nov-30
Inspection Number: 21769090

Inspection Result:

PASS

E18-13

FACILITY:	Inland Truck & Equipment Ltd / S20211	INSP. TYPE:	Complete	INSP. START:	2026-May-12 07:45 AM MDT
INSPECTOR:	JANZEN, EVAN CHAD / 200684	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-May-12 10:45 AM MDT
WORK ORDER #:	358	INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	14991651	VIN:	1XKZD49X2SJ998530
PLATE #:	71892P	UNIT/FLEET#:		OWNER/LESSEE NAME:	ROYAL BANK OF CANADA (LSR), columbia valley freight ltd (LSE)
LICENCED GWV(kg):	46500	BODY STYLE:	Truck Tractor	ADDRESS:	114 INDUSTRIAL 2 RD Invermere, British Columbia v0a1k5, Canada
VEHICLE YEAR:	2025	ODOMETER:	174365 KM		
MAKE:	KENWORTH	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed with Caution
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

STEER TIRES WORN TO EXCESS, CUSTOMER WILL BRING TO TIRE SHOP.

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)		Inner L	Inner R	Outer R	Steering
1	Disc	N/A	Not Applicable	0	0	0				0	✓
2	Disc	N/A	Not Applicable	0	0	17		17	17	17	
3	Disc	N/A	Not Applicable	0	0	15		15	15	15	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right	Brake Lining/Pad (mm)		Left	Right	Rotor Thickness or Drum Inside Diameter (mm)		
			Lining/Pad				Rotor/Drum	Left	Right
1	0	0	Pad		18	18	Drum		
2	0	0	Pad		19	19	Drum		
3	0	0	Pad		19	19	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: JANZEN, EVAN CHAD
Road Test Date: 
Signature: _____ Road Tester:

This Inspection Report was submitted to CVSE on 2026-May-12 10:45 AM MDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

5/12/2026 10:45:38 AM MDT