



Commercial Vehicle Inspection Report

Decal Number: GP89437
Decal Expiry Date: 2027-Sep-30
Inspection Number: 21912366

Inspection Result:
PASS

FACILITY: C & T REPAIRS / S5003 INSP. TYPE: Complete INSP. START: 2026-Sep-03 03:00 PM PDT
INSPECTOR: SARNOWSKI, CHRISTOPHER JOHN INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2026-Sep-03 04:40 PM PDT
/ 106198
WORK ORDER #: 26037 INSP. REASON: Annual

VEHICLE JUR: British Columbia REGI: 10841909 VIN: 2A9LB553XDN125232
PLATE #: 73972U UNIT/FLEET#: OWNER/LESSEE NAME: 532364 BC Ltd, Pioneer Logging
LICENCED GVW(kg): 999999 BODY STYLE: Lowbed Trailer ADDRESS: 197A Fourth AveS, 197A Fourth AveS
VEHICLE YEAR: 2013 ODOMETER: Williams Lake, British Columbia
MAKE: ASPEN HUB ODOMETER: V2G1J8, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) 2R Brake 2R Maxi
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	48	44	7	4	10	11	
2	Clamp	30	Automatic	38	38	9	11	15	15	
3	Clamp	30	Automatic	44	38	11	11	10	9	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	40	60
2	85	30
3	45	55

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	21	17
Lining (Shoe)	15	21
Lining (Shoe)	20	20

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date:

Road Tester:

Inspector: SARNOWSKI, CHRISTOPHER JOHN Signature: 

This Inspection Report was submitted to CVSE on 2026-Sep-09 11:21 AMPDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

Pioneer 2013 ASPEN Bad

Exp Sept 30 2027

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement

CVSE0014

9/9/2026 11:21:26 AM PDT