



Commercial Vehicle Inspection Report

Decal Number: GN84962
Decal Expiry Date: 2027-Apr-30
Inspection Number: 21956436

Inspection Result:
PASS

FACILITY: PETERBILT PACIFIC INC. / S20198
INSPECTOR: Schroeder, Lawrence Francis / 112097
WORK ORDER #: CN6907
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual
INSP. START: 2026-Oct-16 07:30 AM MST
INSP. COMPLETE: 2026-Oct-16 10:00 AM MST

616-3

VEHICLE JUR: British Columbia
PLATE #: 74291U
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2009
MAKE: K-LINE
MODEL:
REGI: 10651561
UNIT/FLEET#: BTRAIN PUP
BODY STYLE: Dump Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2K9DP22929L052179
OWNER/LESSEE NAME: SHA-DAINE, HOLDINGS LTD
ADDRESS: 212 COLLIS ST
Creston, British Columbia
V0B1G6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACED SNAP RINGS ON #1 AXLE S-CAMS
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) REPLACED LICENSE PLATE LAMP AND LEFT TAIL LAMP
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) REPAIRED CRACKS IN DUMP BODY AND #2 CROSSMEMBER
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	40	40
2	Clamp	30	Automatic	40	40

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
16	16	5	4	
9	8	14	14	

Comment: NOTE CAUTION #1 RIGHT AXLE TIRES GETTING LOW ON TREAD BUT STILL IN SPEC. WILL LET CUSTOMER KNOW

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	35	40
2	75	45

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	19	19
Lining (Shoe)	17	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? Yes
Inspector: Schroeder, Lawrence Francis
Road Test Date: Before Inspection
Signature: Lawrence Schroeder
Road Tester: LAWRENCE SCHROEDER

This Inspection Report was submitted to CVSE on 2026-Oct-16 10:55 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

10/16/2026 10:55:46 AM MST