



Commercial Vehicle Inspection Report

Decal Number: GN78782
Decal Expiry Date: 2027-Jan-31
Inspection Number: 21858265

Inspection Result:
PASS

FACILITY: PETERBILT PACIFIC INC. / S12500 INSP. TYPE: Complete INSP. START: 2026-Jul-23 03:50 PM PDT
INSPECTOR: ARCHER, AIDEN / 300969 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW INSP. COMPLETE: 2026-Jul-23 04:50 PM PDT
WORK ORDER #: TB50999 INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 12144319 VIN: 1XPCDP0X3HD445942
PLATE #: KX3865 UNIT/FLEET#: 58 OWNER/LESSEE NAME: PROGRESSIVE VENTURES, PROGRESSIVE VENTURES
LICENCED GVW(kg): 47000 BODY STYLE: Dump Truck ADDRESS: 5008 POHLE AVE SUITE 4, 5008 POHLE AVE SUITE 4, 5008 POHLE AVE S
Terrace, British Columbia
VEHICLE YEAR: 2017 ODOMETER: 473412 KM V8G4S8, Canada
MAKE: PETERBILT HUB ODOMETER:
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) -REPLACED ENGINE BELTS
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) -REPLACED #2 AXLE RIGHT BRAKE CHAMBER
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) -REPLACED RIGHT MIDDLE ROOF MARKER
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) -SECURED PASSENGER SIDE STEP/ COVER
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Disc	N/A	Not Applicable	0	0
2	Clamp	30L	Automatic	38	38
3	Clamp	30L	Automatic	40	35

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
	15			15	✓
	21	21	22	21	
	20	19	19	20	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	0	0
2	20	20
3	75	50

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Pad	16	16
Lining (Shoe)	21	21
Lining (Shoe)	14	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	41.20	41.73
Drum	0.00	0.00
Drum	0.00	0.00

Comment: -MEASURED STEER AXLE ROTORS, DRIVE AXLE DRUMS NOT REMOVED

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Road Tester:

Inspector: ARCHER, AIDEN

Signature:

This Inspection Report was submitted to CVSE on 2026-Jul-23 04:52 PMPDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

7/23/2026 4:52:41 PM PDT