

533-2



Commercial Vehicle Inspection Report

Decal Number: GR12525
Decal Expiry Date: 2027-Apr-30
Inspection Number: 21952976

Inspection Result:
PASS

FACILITY:	PETERBILT PACIFIC INC. / S12500	INSP. TYPE:	Complete	INSP. START:	2026-Oct-13 10:00 AM
INSPECTOR:	ARCHER, AIDEN / 300969	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Oct-13 11:30 AM
WORK ORDER #:	TB51367	INSP. REASON:	Semi-annual		Coordinated Universal Time
VEHICLE JUR:	British Columbia	REGI:	11863601	VIN:	1NPCLP0X2HD416008
PLATE #:	KP4475	UNIT/FLEET#:	46	OWNER/LESSEE NAME:	PROGRESSIVE VENTURES CONSTRUCTION LTD, PROGRESSIVE VENTURES CONSTRUCTION LTD
LICENCED GVW(kg):	47000	BODY STYLE:	Dump Truck	ADDRESS:	5008 POHLE AVE SUITE 4, 5008 POHLE AVE SUITE 4 Terrace, British Columbia V8G4S8, Canada
VEHICLE YEAR:	2017	ODOMETER:	397850 KM		
MAKE:	PETERBILT	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Repaired (same day)	-REPAIRED COOLANT LEAK
Section 1 - Power Train	Passed	
Section 2 - Suspension	Repaired (same day)	-REPLACED #2 AXLE LEFT TRACKING ROD
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	-REPAIRED AIR LEAK AT #2 AXLE
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	-REPAIRED LEFT HEADLIGHT TURN SIGNAL
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	-REFRESHED REFLECTIVE MARKINGS ON TAILGATE
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Disc	N/A	Not Applicable	0	0	13			14	✓
2	Clamp	30L	Automatic	35	30	18	17	17	16	
3	Clamp	30L	Automatic	35	35	15	16	14	17	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	0	0	Pad	14	14	Rotor	39.98	40.85
2	85	90	Lining (Shoe)	14	13	Drum	0.00	0.00
3	80	90	Lining (Shoe)	14	13	Drum	0.00	0.00
Comment:			Comment:			Comment:		

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: ARCHER, AIDEN
Road Test Date: 2026-09-13
Signature: A. Archer
Road Tester:

This Inspection Report was submitted to CVSE on 2026-Oct-13 05:19 PM Coordinated Universal Time
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.
The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement
CVSE014
10/13/2026 5:19:13 PM Coordinated Universal Time