



Commercial Vehicle Inspection Report

Decal Number: GN12768
Decal Expiry Date: 2027-Apr-30
Inspection Number: 21962732

Inspection Result:
PASS

FACILITY:	CABER INDUSTRIES / S12170	INSP. TYPE:	Complete	INSP. START:	2026-Oct-21 10:15 AM PDT
INSPECTOR:	QUANE, LIAM / 301718	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Oct-21 03:12 PM PDT
WORK ORDER #:	029	INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	12274631	VIN:	1XKDD40X6CJ950229
PLATE #:	PV8704	UNIT/FLEET#:	T-05	OWNER/LESSEE NAME:	STOREY'S EXCAVATING LTD., STOREYS
LICENCED GVW(kg):	63500	BODY STYLE:	Truck Tractor	ADDRESS:	507 11th Ave E
VEHICLE YEAR:	2012	ODOMETER:	647860 KM		Prince Rupert, British Columbia
MAKE:	KENWORTH	HUB ODOMETER:			V8J2W6, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) 1L+R SHOCK, 2L+R SHOCK ABSORBER
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) 3L+R BRAKE CHAMBER, 2L AIR LINE SECURE/ RUBBING
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Repaired (same day) 1R WHEEL SEAL
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	38.1	31.8	17.5			16.7	✓
2	Clamp	30L	Automatic	31.8	31.8	18.3	17.5	18.3	17.5	
3	Clamp	30L	Automatic	38.1	38.1	15.9	17.5	16.7	15.9	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	50	45	Lining (Shoe)	12	12	Drum		
2	45	45	Lining (Shoe)	14	14	Drum		
3	40	40	Lining (Shoe)	18	18	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:

Inspector: QUANE, LIAM Signature:

This Inspection Report was submitted to CVSE on 2026-Oct-21 06:13 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.