



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	MUR-CAL SERVICES LTD		
Address:	PO BOX 1308 STN. MAIN		
City:	GRANDE PRAIRIE	Province:	AB
		Postal Code:	T8V 4Z1
Telephone Number:	(780) 402-1547		
Vehicle Identification Number:	2C9GSS3Z7JM183281		
Make:	Gerry's	Model:	Logger-Lead
Year:	2018	Unit Number:	1522LT
Odometer:	KM	Licence Plate Number:	6WF686
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Pro-Ex Equipment Repairs Ltd.	12897
Inspection Technician Name:	Technician Number:
Miles Payeur	A4638
Inspection Technician Signature:	
Inspection Date:	2026/01/13

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle Trailer															Gross Vehicle Weight registered kg														
Vehicle Information																													
VIN 2 C 9 G S S 3 Z 7 J M 1 8 3 2 8 1					Unit Number 1522LT					Year 2018					Make Gerry's					Model Logger-Lead					Odometer				
Registered Owner's Name MUR-CAL SERVICES LTD																				Plate Number 6WF686									
Address PO BOX 1308 STN. MAIN															Postal Code T8V 4Z1					Phone Number (780) 402-1547									
Drum Brakes: A-Full Inspection with Drum Removed Disc Brakes:																													

LEFT		FRONT		RIGHT	
100 psi	100 psi	419.10 mm	Drums/Rotors	419.10 mm	100 psi
15 mm	12 mm	21 mm	Linings/Pads	21 mm	100 psi
		35 mm	Push Rod Travel	35 mm	9 mm
100 psi	100 psi	419.10 mm	Drums/Rotors	419.10 mm	100 psi
12 mm	17 mm	21 mm	Linings/Pads	21 mm	100 psi
		35 mm	Push Rod Travel	35 mm	12 mm
100 psi	100 psi	419.10 mm	Drums/Rotors	419.10 mm	100 psi
12 mm	17 mm	21 mm	Linings/Pads	21 mm	100 psi
		35 mm	Push Rod Travel	35 mm	12 mm
psi	psi	mm	Drums/Rotors	mm	psi
mm	mm	mm	Linings/Pads	mm	mm
		mm	Push Rod Travel	mm	mm
psi	psi	mm	Drums/Rotors	mm	psi
mm	mm	mm	Linings/Pads	mm	mm
		mm	Push Rod Travel	mm	mm
psi	psi	mm	Drums/Rotors	mm	psi
mm	mm	mm	Linings/Pads	mm	mm
		mm	Push Rod Travel	mm	mm

Park Brake Lining Left N/A mm Right N/A mm Trans N/A mm
 Wheel Torque Checked ☒ Inner N/A ft lbs Outer 500 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train							
Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System				1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A *			

NOTES:

APPENDIX "A"							
Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System				A.3. Liquefied Natural Gas (LNG) Fuel System			
A.2. Compressed Natural Gas (CNG) Fuel System							

NOTES:

Section 2 - Suspension							
Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments				2.5. Air Suspension			
2.2. Axle Attaching & Tracking Components				2.6. Self-Steer & Controlled-Steer Axle			
2.3. Axle & Axle Assembly				2.7. Shock Absorber/Strut Assembly			
2.4. Spring & Spring Attachment							

NOTES:

CROSSMEMBERS ABOVE AXLE 1 AND AXLE 2 REPLACED
REPAIRED CRACKS IN CROSSMEMBERS AHEAD OF SUSPENSION

Section 3H - Hydraulic Brakes							
Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components				3H.10. Electric Brake System			
3H.6. Air-Over-Hydraulic Brake System				3H.12. Drum Brake System Components			
3H.7. Surge Brake Controller				3H.13. Disc Brake System Components			
3H.8. Vacuum System				3H.19. Brake Performance			
3H.9. Air-Boosted Trailer Brake System							

NOTES:

Section 3A - Air Brakes							
Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage				3A.16. S-Cam Drum Brake System			
3A.4. Air Tank				3A.17. Brake Shoe Travel (Wedge Brakes)			
3A.8. Brake Valves & Controls				3A.18. Disc Brake System Components			
3A.12. Parking Brake & Emergency Application				3A.20. Anti-Lock Brake System (ABS)			
3A.13. Air System Components				3A.22. Stability Control System (ESC) or (RSS)			
3A.14. Brake Chamber				3A.23. Brake Performance			
3A.15. Drum Brake System Components							

NOTES:

REPLACED BOTH BRAKE BOTS ON AXLE 3
REPLACED BRAKE POT AXLE 1 I/h SIDE
REPLACED ALL 6 BRAKE DRUMS
REPLACED ALL 6 SETS OF BRAKE SHOES
REWIRE ABS SYSTEM TO GET ALL WORKING AS REQUIRED

Section 4 - Steering							
Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage				4.5. Self Steer & Controlled-Steer Axle			
4.4. Kingpin							

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

NOTES:

Section 5 - Instruments and Auxiliary Equipment							
Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps							
Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps				6.3. Retro-Reflective Marking			
6.2. Reflex Reflector	✓				✓		

NOTES:

REPLACED LICENSE PLATE LIGHT
REPAIR WIRING TO R/H BRAKE LIGHTS
REPLACED REFLECTIVE TAPE ON LOG BUNKS

Section 7 - Electrical System							
Component	P	F	NA	Component	P	F	NA
7.1. Wiring				7.3. Trailer Cord (output to towed vehicle)			
7.2. Battery	✓				✓		

NOTES:

REPLACE SOCKET ON BACK OF TRAILER FOR PUP TO HOOK UP TO IT

Section 8 - Body							
Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body				8.11. Refrigeration/Heater Unit Fuel System			
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap			
8.7. Unitized Body Elements	✓			8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door				8.23. Sliding Axle Assembly (Sliding Bogie)	✓		
8.9. Cargo Tank or Vessel				8.24. Aerodynamic Device & Attachment			
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.25. Rear Impact Guard (RIG)			

NOTES:

Section 9 - Tires and Wheels							
Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓		
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

3 TIRES WERE REPLKACED DUE TO STONE DRILLING
AXLE 1 R/H OUTSIDE RIM REPLACED DUE TO CRACK IN RIM

Section 10 - Couplers and Hitches							
Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			
10.2. Secondary Attachment (Safety Chain or Cable)				10.7. Fifth Wheel Coupler	✓		

Page 3 of 4

P=PASS F=FAIL NA=Not Applicable

VSSRO/2018

Section 10 - Couplers and Hitches			
Component	P	F	NA
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			
10.4. Ball Type Hitch			
10.5. Roll-Coupling Hitch			

Component	P	F	NA
10.8. Oscillating Fifth Wheel Coupler			
10.9. Ball-Bearing Type Turntable on Trailer			

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8356120) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number
2026/01/13	A4638	12897

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Signature

[Signature]

Date (Year/Month/Day)

2026/01/13

Customer Signature