



Commercial Vehicle Inspection Report

Decal Number: CC08367
Decal Expiry Date: 2025-Mar-31
Inspection Number: 20872483

Inspection Result:

PASS

FACILITY: MOGA TRUCK REPAIR / S5914
INSPECTOR: BRAR, GAGANDEEP SINGH / 203058
WORK ORDER #: 16491
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2024-Mar-28 01:15 PM PDT
INSP. COMPLETE: 2024-Mar-28 02:15 PM PDT

VEHICLE JUR: British Columbia
PLATE #: 17227J
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2015
MAKE: LOAD KING
MODEL:
REGI: 11395344
UNIT/FLEET#: m15a
BODY STYLE: Flat Deck Trailer
VIN: 2LDPF3231FJ060405
OWNER/LESSEE NAME: MANNEY TRANSPORT LTD. PO BOX 8000 STN DEL CTR
ADDRESS: PO BOX 8000 STN DEL CTR, PO BOX 8000 STN DEL CTR
Abbotsford, British Columbia
V2S6H1, Canada
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	32	31
2	Clamp	30	Automatic	34	33
3	Clamp	30	Automatic	32	32

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
1	12	12	13	14	
2	6	9	8	9	
3	9	8	8	10	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	57	50
2	30	35
3	35	45

Comment:

Brake Lining/Pad (mm)

	Lining/Pad	Left	Right
1	Lining (Shoe)	18	19
2	Lining (Shoe)	20	20
3	Lining (Shoe)	19	19

Comment:

Rotor Thickness or Drum inside Diameter (mm)

	Rotor/Drum	Left	Right
1	Drum		
2	Drum		
3	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: BRAR, GAGANDEEP SINGH

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2024-Mar-30 11:16 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

3/30/2024 11:16:20 AM PDT