

Date Inspection Started
09 DAY 04 MO. 25 YR.

Date Inspection Completed
09 DAY 04 MO. 25 YR.

Inspection Expiry Date
09 DAY 04 MO. 26 YR.

Station Number
A0509

Station Name
Schoof Service

Mechanic Number
M191014

Mechanic Signature
Craig Barnette

Station Phone Number
204-242-2785

Vehicle Owner
Suban

Address
150 Front Ave

City
Manitoba

Province
MB

Postal Code
R0G 1G0

Phone
242-2845

☒ Pass/Safe Vehicle

☐ Fail/Unsafe Vehicle

☐ Fail/Hazardous

Licence Number
C4M1184

Prov.
MB

NSC #
MB9027700

Odometer Reading
204103

Odom. Type
☒ km ☐ mi

Vehicle Identification Number
1G1D41211C611F565806

Make
GMC

Model
3500

Year
2015

Unit #
ST44

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

☒ Truck

GVWR
15918

KGS

☐ Truck Tractor

☐ Trailer

☐ Semi-Trailer

☐ Bus

☐ School Bus

☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																						
X		Section 2 Suspension: Defects (if any)																																																																						
X		Section 3 - Brake Systems: Defects (if any) 3H 3A Circle Brake Type																																																																						
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table><thead><tr><th rowspan="2">Axle</th><th colspan="2">Lining</th><th colspan="2">Drum/Rotor</th><th colspan="2">Stroke</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>6.18</td><td>6.26</td><td>39.59</td><td>39.64</td><td></td><td></td></tr><tr><td>2</td><td>4.22</td><td>4.15</td><td>39.60</td><td>39.61</td><td></td><td></td></tr><tr><td>3</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td colspan="7">Final Measurement</td></tr></tbody></table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	6.18	6.26	39.59	39.64			2	4.22	4.15	39.60	39.61			3							4							5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	6.18	6.26	39.59	39.64																																																																				
2	4.22	4.15	39.60	39.61																																																																				
3																																																																								
4																																																																								
5																																																																								
Final Measurement																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X		Section 6 - Lamps: Defects (if any)																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X		Section 8 - Body: Defects (if any)																																																																						
X		Section 9 - Tire & Wheel: Defects (if any) 4-A Tire Pressure																																																																						
		<table><thead><tr><th rowspan="3">Axle</th><th colspan="4">Tread Depth</th><th colspan="4">Air Pressure</th></tr><tr><th colspan="2">Initial</th><th colspan="2">Corrected</th><th colspan="2">Initial</th><th colspan="2">Corrected</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>10.27</td><td>8.95</td><td></td><td></td><td>40</td><td>40</td><td></td><td></td></tr><tr><td>2</td><td>4.29</td><td>4.22</td><td>4.51</td><td>4.25</td><td>60</td><td>60</td><td>55</td><td>55</td></tr><tr><td>3</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	10.27	8.95			40	40			2	4.29	4.22	4.51	4.25	60	60	55	55	3									4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	10.27	8.95			40	40																																																																		
2	4.29	4.22	4.51	4.25	60	60	55	55																																																																
3																																																																								
4																																																																								
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

 Date: