

Commercial Vehicle Inspection Report

Decal Number: **Decal Expiry Date:** Inspection Number:

GJ53969 2025-Oct-31 21329205

Inspection Result:

ARSARA DIESEL TRUCK / S5708 2025-Apr-28 04:15 PM PDT FACILITY: INSP. TYPE: Complete INSP. START: INSPECTOR: SALL, JASWANT SINGH / 112148 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW INSP. COMPLETE: 2025-Apr-29 01:17 AM PDT 5501 kg or more WORK ORDER #: INSP. REASON: Semi-annual 4V4NC9KJX7N477298 VEHICLE JUR: British Columbia REGI: 02913666 VIN: PLATE #: WG5314 UNIT/FLEET#: 346 OWNER/LESSEE NAME: BOPARAI, BALRAJ SINGH LICENCED GVW(kg): 46500 BODY STYLE: Truck Tractor ADDRESS: 8745 151B ST VEHICLE YEAR: 2007 ODOMETER: 1825076 KM Surrey, British Columbia MAKE: **VOLVO** HUB ODOMETER: V3S4Z2, Canada MODEL: BRAKE TYPE: Air **FUEL TYPE:** Diesel

Vehicle Identification (VIN) Passed Section 1 - Power Train Repaired (same day)

Section 2 - Suspension Repaired (same day) Section 3 - Brake System

AXLE#2 B\S SHOCK AND L\S U BOLTS Passed

HOSE CLAMP LOOSE

Section 3A - Air Brakes Repaired (same day) Section 3H - Hydraulic Brakes Not Applicable

ADJ CLUTCH, COOLANT LEAK, STEADY BEARING, CAUTION-DRIVE LINE

AXLE#2 AND#3 L\S PIGGY BACK.AXLE#1 L\S BRAKE SHOE

Section 5 - Instruments and Auxiliary Equipment

Section 4 - Steering

Section 6 - Lamps

REP AS REQ Repaired (same day)

Repaired (same day)

Passed

Section 7 - Electrical System Passed Section 8 - Frame and Body

L\S SLEEPER FAIRING AND HOOD SHOCK Repaired (same day)

Passed Section 9A - Tires Passed Section 9B - Wheels Section 10 - Coupling Devices Passed Section 11 - Other Vehicle Components Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Туре	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	31	31	12			12	~
2	Clamp	30	Automatic	38	38	17	17	17	17	
3	Clamp	30	Automatic	38	38	17	17	17	17	
Comment:						Comment:				

Air Brake Camsha	ft Rotation (degr	ees)	Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	70	70	Lining (Shoe)	14	14	Drum	0.00	0.00	
2	70	70	Lining (Shoe)	15	15	Drum	0.00	0.00	
3	65	65	Lining (Shoe)	15	15	Drum	0.00	0.00	
Comment:			Comment:	Comment:					

Inspection Comments:

Road Test Date: Has this Vehicle been road tested? SALL, JASWANT SINGH Signature:

This Inspection Report was submitted to CVSE on 2025-Apr-29 01:17 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.