C08-1

Commercial Vehicle Inspection Report

BRITISH COLUMBIA

Decal Number:	GM90256
Decal Expiry Date:	2027-Mar-31
Inspection Number:	21696864

Inspection Result: **PASS**

2026282

FACILITY:	J & G FLEET SERVICES LTD / S16741	**INSP. TYPE:**	Complete	**INSP. START:**	2026-Mar-14 08:24 AM PDT
INSPECTOR:	HODGSON, LARRY THOMAS / 104565	**INSP. CLASS:**	Class 3 - Trailer and Semi-Trailer	**INSP. COMPLETE:**	2026-Mar-14 02:25 PM PDT
WORK ORDER #:	22476	**INSP. REASON:**	Annual		

VEHICLE JUR:	British Columbia	**REGI:**	00258807	**VIN:**	1UYVS25347G219433
PLATE #:	35294J	**UNIT/FLEET#:**	0791	**OWNER/LESSEE NAME:**	REDUX NUTRITION LTD, REDUX
LICENCED GVW(kg):	999999	**BODY STYLE:**	Van Trailer	**ADDRESS:**	1292 VENABLES ST, 1292 VENABLES ST
VEHICLE YEAR:	2007	**ODOMETER:**			Vancouver, British Columbia
MAKE:	UTILITY	**HUB ODOMETER:**			V6A4B4, Canada
MODEL:		**BRAKE TYPE:**	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Not Applicable	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	**Passed with Caution**	WALL DAMAGE
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	**Passed with Caution**	KING PIN NEERING END OF LIFE
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	48	44
2	Clamp	30	Automatic	48	48

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
12	12	7	7	
7	8	10	9	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	60	95
2	90	90

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	16
Lining (Shoe)	17	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**

Inspector: HODGSON, LARRY THOMAS **Signature:**

This Inspection Report was submitted to CVSE on 2026-Mar-14 02:25 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

3/14/2026 2:25:52 PM PDT