

NWM736 - Maintenance History				
Close Date	Job Id	Odometer	Category	Description
7/04/2022	5	671	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
12/04/2022	8	671	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
17/05/2022	17	1094	Maintenance	Rollers Replaced
19/04/2022	18	798	Maintenance	Id Sign Replaced
4/05/2022	22	1094	Maintenance	Repaired Leak In Grease System
4/05/2022	33	2076	Routine Service	Nwm736 - 1000 Hour 8 Weekly Service (Hitachi)
11/05/2022	45	1094	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
20/05/2022	70	1377	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
14/06/2022	74	1740	Maintenance	Replaced Grease Nipple
8/06/2022	102	1624	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
10/06/2022	113	1740	Maintenance	A/C Belt And Drive Belt Replacement
6/07/2022	116	2076	Maintenance	Replace Damaged Bucket
27/06/2022	118	1838	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
6/07/2022	119	2076	Maintenance	Replace Final Drive Oil
1/08/2022	133	2411	Maintenance	Bucket Repair, Refit Cylinders With New Pin, Replace Grease Nipples Grease Unit, Refit New Hydraulic Lines, Flip Cutting Edge And Install New Mounting Hardware
1/07/2022	141	2076	Routine Service	Nwm736 - 1000 Hour 8 Weekly Service (Hitachi)
22/07/2022	181	2411	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
17/08/2022	200	2850	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
30/08/2022	228	2881	Maintenance	Repaired Bucket
5/09/2022	236	2881	Maintenance	Change Bucket For Tilt
5/09/2022	236	2881	Routine Service	Nwm736 - 1000 Hour 8 Weekly Service (Hitachi)
19/09/2022	259	1172	Site Compliance	Fire Suppression Service
19/09/2022	259	1172	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
7/10/2022	274	3289	Maintenance	Fabrication Repairs - Step, Handrail And Platform.
7/10/2022	274	3289	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
7/10/2022	312	3543	Maintenance	Change Hydraulic Oil
7/10/2022	312	3543	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
7/10/2022	317	1172	Maintenance	Inspect And Fix Overload Fault
8/11/2022	325	4040	Maintenance	Replace Step.
25/11/2022	329	3289	Maintenance	Step, Platform And Rail Repairs.
18/10/2022	337	3769	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
1/11/2022	367	3769	Maintenance	Circuit Breaker Replaced
8/12/2022	375	4411	Maintenance	Auto Grease Fault
16/11/2022	384	3289	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
16/11/2022	384	3289	Maintenance	Replaced Step, Replaced Two Rear Upper Rollers
8/12/2022	405	4240	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
16/12/2022	428	4411	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
19/12/2022	446	4629	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
6/01/2023	473	4789	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
18/01/2023	497	5006	Maintenance	Weld Handrails
18/01/2023	497	5006	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
7/02/2023	514	5229	Routine Service	Nwm736 - 1000 Hour 8 Weekly Service (Hitachi)
28/04/2023	540	5399	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
28/04/2023	540	5399	Maintenance	Replaced 2 Grease Lines.
30/03/2023	568	5911	Maintenance	Replaced New Alternator, Engine Issue - Hitachi Ordered 3 Injectors.
30/03/2023	598	5719	Routine Service	Nwm736 - 1000 Hour 8 Weekly Service (Hitachi)
3/04/2023	631	5911	Routine Service	Nwm736 - 2000 Hour Service (Hitachi)
19/04/2023	689	6102	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
19/04/2023	689	6102	Maintenance	Replaced Two Grease Nipples In The Bucket
19/04/2023	721	6215	Maintenance	Fitted New Beacon
28/04/2023	735	6329	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
24/05/2023	744	5395	Maintenance	Replaced Stick Hydraulic Ram
19/05/2023	790	6574	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
19/05/2023	790	6574	Maintenance	Fitted New Upper Rollers, Torqued Up And Fitted Estop
31/05/2023	791	7055	Site Compliance	Fire Suppression Inspection/Service

31/05/2023	834	6817	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
1/06/2023	872	7055	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
30/06/2023	891	7464	Routine Service	Nwm736 - 1000 Hour 8 Weekly Service (Hitachi)
30/06/2023	891	7464	Maintenance	Repair On Wiring Harness And Reset Grease Fault
12/07/2023	939	7737	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
17/07/2023	952	7871	Maintenance	Replace With New Door Seal
31/07/2023	979	8004	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
31/07/2023	979	8004	Maintenance	Replaced Grease Nipples In Bucket
31/08/2023	1007	8642	Maintenance	Fab Repairs On Fire Suppression Mounts And Fit New Bracket And Refit Bottle.
3/08/2023	1022	8252	Routine Service	Nwm736 - 1000 Hour 8 Weekly Service (Hitachi)
16/08/2023	1033	8351	Maintenance	Fabricated Hose For Digger Boom
24/08/2023	1049	8474	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
24/08/2023	1049	8474	Maintenance	Replaced Fire Suppression Bracket
31/08/2023	1090	8671	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
19/09/2023	1136	8933	Routine Service	Nwm736 - 1000 Hour 8 Weekly Service (Hitachi)
28/09/2023	1144	8996	Maintenance	Reinstalled Hose Over Boom And Refilled Hydraulic Oil.
3/10/2023	1191	8996	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
20/10/2023	1224	9422	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
8/11/2023	1248	9422	Maintenance	Inspect Rod In Hydraulic Tank - No Damage
9/11/2023	1249	9422	Maintenance	Fit And Seg New Hydraulic Hose
6/11/2023	1253	9422	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
6/11/2023	1273	9422	Maintenance	Replaced Primary And Secondary Air Filters.
4/01/2024	1283	10479	Maintenance	Leaking Engine Sump
16/11/2023	1300	9422	Maintenance	Replaced E-Stop
16/11/2023	1300	9422	Routine Service	Nwm736 - 1000 Hour 8 Weekly Service (Hitachi)
1/12/2023	1328	10178	Maintenance	Repaired Broken And Bent Platform
1/12/2023	1328	10178	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
5/12/2023	1352	10479	Maintenance	Repaired Damaged Walkway
18/12/2023	1372	10479	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
18/12/2023	1378	10479	Maintenance	Fit New Hose
31/12/2023	1407	10479	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
31/01/2024	1420	11080	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
15/01/2024	1441	10479	Site Compliance	Fire Suppression Inspection/Service
15/01/2024	1441	10479	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
12/01/2024	1444	10479	Site Compliance	Fire Suppression Inspection/Service
31/01/2024	1464	11080	Maintenance	Refit Carry Roller
31/01/2024	1465	11080	Maintenance	Replaced Injection Pump Primer
15/02/2024	1502	11284	Routine Service	Nwm736 - 1000 Hour 8 Weekly Service (Hitachi)
29/02/2024	1530	11543	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
14/03/2024	1574	11785	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
31/03/2024	1577	12075	Maintenance	Refit Carry Rollers
31/03/2024	1577	12075	Maintenance	Refit Track To Machine.
8/05/2024	1602	12285	Maintenance	Installed New Grease Pump
3/04/2024	1606	11990	Maintenance	Refit New Starter Mortor
30/04/2024	1608	12285	Routine Service	Nwm736 - 1000 Hour 8 Weekly Service (Hitachi)
30/04/2024	1644	12285	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
30/04/2024	1644	12285	Maintenance	Removed And Replaced Cutting Edge Boltsand Welded On.
30/04/2024	1666	12285	Routine Service	Nwm735 - 1000 Hour 8 Weekly Service (Hitachi)
20/05/2024	1693	12937	Routine Service	Nwm736 - 1000 Hour 8 Weekly Service (Hitachi)
6/06/2024	1722	13068	Maintenance	Replaced Track Adjuster Valves
31/05/2024	1726	12937	Routine Service	Nwm736 - 1000 Hour 8 Weekly Service (Hitachi)
6/06/2024	1754	13068	Maintenance	Carried Out Slew Box Rebuild, New Seals And Bearing Installed Refit Into Machine. Remove And Replace Worn Turbo Lagging Remove And Replaced Leaking Injector Lines
31/05/2024	1805	13068	Maintenance	Upper Rollers Change.
31/05/2024	1806	13068	Maintenance	Replace Damaged Adjuster And Reassamble Track Assembly
9/08/2024	1818	14072	Maintenance	Fit Replacement Hydraulic Hose. Fixed Blown A/C Hose.
2/08/2024	1821	13241	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
31/07/2024	1845	14072	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
31/07/2024	1862	14072	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)

31/07/2024	1907	14072	Routine Service	Nwm736 - 1000 Hour 8 Weekly Service (Hitachi)
31/07/2024	1914	14072	Maintenance	Refit Track To Machine, Refit Roller And Adjusted Track
5/08/2024	1920	14072	Maintenance	Fit New Alternator
2/09/2024	1939	14072	Maintenance	Adjusted Track
9/09/2024	1944	14260	Site Compliance	Fire Suppression Inspection/Service
31/08/2024	1963	14260	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
30/09/2024	2004	14260	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
30/09/2024	2004	14260	Site Compliance	Pressure Vessel Inspection
30/09/2024	2018	14260	Maintenance	Fit New Hose
30/09/2024	2018	14260	Routine Service	Nwm736 - 1000 Hour 8 Weekly Service (Hitachi)
25/10/2024	2058	14260	Routine Service	Nwm736 - 1000 Hour 8 Weekly Service (Hitachi)
30/12/2024	2060	16297	Maintenance	Stick Repair
13/01/2025	2144	15175	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
13/01/2025	2144	15175	Site Compliance	Fire Suppression Inspection/Service
13/01/2025	2144	15175	Maintenance	Replaced Ac Compressor Recharged System, Undercarriage Repairs - Rebuild
7/01/2025	2266	16297	Maintenance	Refit Replacement Alternator
31/01/2025	2282	16297	Maintenance	Fit Replacement Hose To Boom And Refilled Hydraulic Oil
31/01/2025	2284	15175	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
31/01/2025	2304	15675	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
31/01/2025	2342	15675	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
24/02/2025	2348	15709	Maintenance	Slew box Issue
7/03/2025	2385	15817	Maintenance	Removed Stick Cylinder
31/03/2025	2410	16485	Maintenance	Repair, Reconnect And Tested Broken Grease Line To Rh Boom Cylinder
31/03/2025	2410	16485	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
31/03/2025	2460	16485	Maintenance	Water Separator Light Sump Leak Stick Hose Leak Slew box Leak
31/03/2025	2460	16485	Routine Service	Nwm736 - 500 Hour 4 Weekly Service (Hitachi)
25/03/2025	2468	16485	Maintenance	Replacement Slew Box
17/04/2025	2503	16691	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
30/04/2025	2515	16282	Maintenance	Reinstall Rebuild Cylinder
30/04/2025	2551	16282	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
30/04/2025	2551	16282	Maintenance	Replaced Broken Emergency Stop
29/04/2025	2560	16282	Maintenance	Replaced Alternator
31/05/2025	2588	16282	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)
31/05/2025	2588	16282	Maintenance	Replaced Dip Stick Tube
10/06/2025	2618	17282	Routine Service	Nwm736 - 250 Hour 2 Weekly Inspection (Hitachi)