



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GJ77962
Decal Expiry Date: 2026-Oct-31
Inspection Number: 21722978

Inspection Result:
PASS

FACILITY:	XCEED TRUCK & TRAILER REPAIR LTD./S20322	INSP. TYPE:	Complete	INSP. START:	2026-Apr-03 08:00 AM PDT
INSPECTOR:	MURTI, KAILESH / 113141	INSP. CLASS:	Class 4 - Bus	INSP. COMPLETE:	2026-Apr-03 11:00 AM PDT
WORK ORDER #:		INSP. REASON:	Semi-annual		

VEHICLE JUR:	British Columbia	REGI:	04520905	VIN:	2PCH33417V1011961
PLATE #:	A2F7V7	UNIT/FLEET#:	961	OWNER/LESSEE NAME:	WESCAN TOURS LTD, WESCAN TOURS LTD
LICENCED GVW(kg):	21200	BODY STYLE:	Bus	ADDRESS:	2198-8700 MCKIM WAY, 2198-8700 MCKIM WAY
VEHICLE YEAR:	1997	ODOMETER:	215721 KM		Richmond, British Columbia
MAKE:	PREVOST	HUB ODOMETER:	215721 KM		V6X1A5, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Repaired (same day)	REPAIRED MINOR COOLANT LEAKS
Section 2 - Suspension	Passed	
Section 3 - Brake System	Repaired (same day)	CHECK AND ADJUST ALL BRAKES
Section 3A - Air Brakes	Repaired (same day)	REPAIR AIR LINE LEAKING AT 3 AXLE LEFT SIDE BRAKE CHAMBER
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	TIGHTEN LOOSE PASSENGER SEAT MOUNTINGS
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Repaired (same day)	REPAIR LEFT SIDE LOWER WIPER IDLER ARM

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Disc	N/A	Not Applicable	0	0	12			13	✓
2	Clamp	36	Automatic	33	33	10	9	9	8	
3	Disc	N/A	Not Applicable	0	0	10			11	✓
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	0	0	Pad	10	10	Drum	41.34	41.55	
2	30	30	Lining (Shoe)	18	18	Drum	0.00	0.00	
3	0	0	Pad	12	12	Drum	43.12	39.45	
Comment:			Comment:			Comment:			

Inspection Comments:

Has this Vehicle been road tested? Yes **Road Test Date:** Before and After Inspection **Road Tester:** KAILESH MURTI

Inspector: MURTI, KAILESH **Signature:**

This Inspection Report was submitted to CVSE on 2026-Apr-06 02:02 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.