

 RITCHIE BROS. Diagnostic Report
Auctioneers[®]**2019 International LT****Test Information**

Engine	Cummins X15 Signature (15.0)
Engine Serial	CMMNS*6X1u17D1500000000*80036123*18-012
VIN	3HSDZAPR5KN371058
Driveline	Class 8 6x4
Body	Truck-Tractor MDHD: Conventional
Test Time	Oct. 23, 2025, 9:49 a.m.
File Length	42.766 s

Usage

Label	Value	Units
Engine Odometer	872,508	mi
Odometer (Instrument Cluster #1)	872,863	mi
Engine Total Hours of Operation	23,015.4	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	121	%

Engine On/Off

Engine running

Check Engine Light



MIL - Emissions malfunction

Emissions Deleted/Tampered

No

Faults

<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Active	Engine #1	Aftertreatment Diesel Particulate Filter System	Erratic, Intermittent, or Incorrect	3
Previous	Engine #1	Manufacturer Assignable SPN	Voltage Below Normal	1
Previous	Engine #1	Aftertreatment 1 SCR Intake NOx 1	Abnormal Update Rate	1
Previous	Engine #1	Engine Coolant Level 1	Low-moderate severity	11
Previous	Engine #1	Water In Fuel Indicator 1	High-least severe	2
Previous	Shift Console - Primary	Transmission Requested Gear	Out of Calibration	1
Previous	Lighting - Operator Controls	Source Address 33	Abnormal Update Rate	1
Emissions Active	Engine #1	Aftertreatment Diesel Particulate Filter System	Erratic, Intermittent, or Incorrect	3
Emissions Previous	Engine #1	ECU Power Output Supply Voltage #1	Erratic, Intermittent, or Incorrect	4
Emissions Previous	Engine #1	Aftertreatment 1 SCR Intake NOx 1	Abnormal Update Rate	1
Emissions Previous	Engine #1	Manufacturer Assignable SPN	Voltage Below Normal	1
Permanent	Engine #1	Aftertreatment Diesel Particulate Filter System	Erratic, Intermittent, or Incorrect	3