



**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

C54-18

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Electric
Owner Name:	Cooper Equipment Rentals Limited		
Address:	8430 24 ST NW		
City:	Edmonton	Province:	AB
		Postal Code:	T6P 1X8
Telephone Number:	(587) 202-5164		
Vehicle Identification Number:	2BYUG2HB7JR000644		
Make:	Brandt	Model:	UGR1124
Year:	2018	Unit Number:	603644
Odometer:	KM	Licence Plate Number:	6TM183
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Bank Mechanical Ltd.	15051
Inspection Technician Name:	Technician Number:
Gregory Haas	B4788
Inspection Technician Signature:	<i>Gregory Haas</i>
Inspection Date:	2025/08/20

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered							
Trailer										kg							
Vehicle Information																	
VIN	2	B	Y	U	G	2	H	B	7	J	R	0	0	0	6	4	4
Unit Number 603644		Year 2018		Make Brandt			Model UGR1124			Odometer							
Registered Owner's Name Cooper Equipment Rentals Limited												Plate Number 6TM183					
Address 8430 24 ST NW								Postal Code T6P 1X8				Phone Number (587) 202-5164					

Drum Brakes: A-Full Inspection with Drum Removed **Disc Brakes:**

		<u>LEFT</u>	<u>FRONT</u>	<u>RIGHT</u>		
82 psi 11/32 in	82 psi 10/32 in	12.306 in	Drums/Rotors	12.287 in	82 psi 10/32 in	82 psi 11/32 in
		7/16 in	Linings/Pads	7/16 in		
		N/A in	Push Rod Travel	N/A in		
82 psi 9/32 in	82 psi 9/32 in	12.304 in	Drums/Rotors	12.293 in	82 psi 11/32 in	82 psi 11/32 in
		7/16 in	Linings/Pads	7/16 in		
		N/A in	Push Rod Travel	N/A in		
__ psi __ in	__ psi __ in	__ in	Drums/Rotors	__ in	__ psi __ in	__ psi __ in
		__ in	Linings/Pads	__ in		
		__ in	Push Rod Travel	__ in		
__ psi __ in	__ psi __ in	__ in	Drums/Rotors	__ in	__ psi __ in	__ psi __ in
		__ in	Linings/Pads	__ in		
		__ in	Push Rod Travel	__ in		
__ psi __ in	__ psi __ in	__ in	Drums/Rotors	__ in	__ psi __ in	__ psi __ in
		__ in	Linings/Pads	__ in		
		__ in	Push Rod Travel	__ in		

Park Brake Lining Left N/A in Right N/A in Trans N/A in
 Wheel Torque Checked Inner N/A ft lbs Outer 275 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train							
Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓

NOTES:

APPENDIX "A"							
Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

Section 2 - Suspension							
Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension			✓
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle			✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly			✓
2.4. Spring & Spring Attachment			✓				

NOTES:

Section 3H - Hydraulic Brakes							
Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System	✓		
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components	✓		
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components			✓
3H.8. Vacuum System			✓	3H.19. Brake Performance	✓		
3H.9. Air-Boosted Trailer Brake System			✓				

NOTES:

All brakes covered in oil. Breakaway not working. Replaced all brakes. Replaced breakaway battery.

Section 3A - Air Brakes							
Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage			✓	3A.16. S-Cam Drum Brake System			✓
3A.4. Air Tank			✓	3A.17. Brake Shoe Travel (Wedge Brakes)			✓
3A.8. Brake Valves & Controls			✓	3A.18. Disc Brake System Components			✓
3A.12. Parking Brake & Emergency Application			✓	3A.20. Anti-Lock Brake System (ABS)			✓
3A.13. Air System Components			✓	3A.22. Stability Control System (ESC) or (RSS)			✓
3A.14. Brake Chamber			✓	3A.23. Brake Performance			✓
3A.15. Drum Brake System Components			✓				

NOTES:

Section 4 - Steering							
Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle			✓
4.4. Kingpin			✓				

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 5 - Instruments and Auxillary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

Needs new reflective tape. Installed all new reflective tape.

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery	✓						

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body	✓			8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements			✓	8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door	✓			8.23. Sliding Axle Assembly (Sliding Bogle)			✓
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle			✓	8.25. Rear Impact Guard (RIG)	✓		

NOTES:

Toolbox latches broken. Install new latches.

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System			✓
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)	✓			10.7. Fifth Wheel Coupler	✓		
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8450526) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection 2025/08/20	Technician Number B4788	Facility Number 15051	Signature 
---	-----------------------------------	---------------------------------	---

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2025/08/20

Customer Signature