

Commercial Vehicle Inspection Report

Decal Number: **Decal Expiry Date:** Inspection Number:

GK00561 2026-Aug-31 21453222

Inspection Result: PASS

FACILITY:

PLATE #:

MAKE:

MODEL:

MAGNUM TRAILER AND

EQUIPMENT / S0783

GIRVIN, DONALD ARTHUR / 111079

INSP. TYPE: INSP. CLASS: INSP. REASON:

Class 3 - Trailer and Semi-Trailer

INSP. START:

INSP. COMPLETE:

2025-Aug-06 04:10 PM PDT 2025-Aug-07 04:00 PM PDT

INSPECTOR: WORK ORDER #: VEHICLE JUR:

VEHICLE YEAR:

226733

2023

LODE KING

Ontario

REGI:

UNIT/FLEET#:

BODY STYLE:

ODOMETER:

VIN:

2LDSD5328PG072857

OWNER/LESSEE NAME:

BANK OF MOMNTREAL EQUIPMENT LEASING CANADA, BANK OF MONTREAL EQUIPMENT LEASING

CANADA

5750 EXPLORER DR. 3RD FLR

Mississauga, Ontario L4W 0B1, Canada

ADDRESS:

BRAKE TYPE:

FUEL TYPE:

HUB ODOMETER:

Not Applicable

Complete

Annual

Vehicle Identification (VIN)

LICENCED GVW(kg): 8864

Section 1 - Power Train

Section 2 - Suspension

Section 3 - Brake System

Section 3A - Air Brakes Section 3H - Hydraulic Brakes

Section 4 - Steering

Section 5 - Instruments and Auxiliary Equipment

Section 6 - Lamps

Section 7 - Electrical System Section 8 - Frame and Body

Section 9A - Tires Section 9B - Wheels

Section 10 - Coupling Devices Section 11 - Other Vehicle Components Passed

Not Applicable

Passed Passed Passed

Not Applicable Not Applicable

Not Applicable

Passed

Passed Passed

Passed Passed Passed

Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles Size Type Slack Adi. Left 1 Clamp 30 Automatic 36 2 Clamp 30 Automatic

Right 36 36

Outer L Comment:

Tire Tread Depth (mm)

Inner L Inner R Outer R 10 12

Rotor/Drum

Drum

Right

Steering

Comment:

Air Brake Camshaft Rotation (degrees) Axles Left Right 70 72 2 80 60 Comment:

Brake Lining/Pad (mm)

Lining/Pad Lining (Shoe) Lining (Shoe) Comment:

Left Right 12 14 12 13

Drum Comment: Air Brake Camshaft Rotation performed. Rotor

Thickness or Drum Diameter not measured.

Rotor Thickness or Drum Inside Diameter (mm)

10

12

Left

Inspection Comments:

Has this Vehicle been road tested? No GIRVIN, DONALD ARTHUR Inspector:

Road Test Date:

Signature:

Road Tester:

9

5

This Inspection Report was submitted to CVSE on 2025-Aug-07 04:11 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement