

04041208

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

Date Inspection Started DAY 08 MO. 04 YR. 26

Date Inspection Completed DAY 09 MO. 04 YR. 26

Inspection Expiry Date DAY 30 MO. 09 YR. 27

Station Number 60152

ARNOLD BROS TRANSPORT LTD.

C043944

Mechanic Number M10890

Station Name 25 LAZIMULIHE ST City WINNIPEG, MANITOBA R2J 0T8

Mechanic Signature Station Phone Number 204 257 6666

Vehicle Owner ARNOLD BROS TRANSPORT LTD.

Address 25 LAZIMULIHE ST City WINNIPEG, MANITOBA R2J 0T8 Province Postal Code Phone 204 257 6666

Pass/Safe Vehicle

Fail/Unsafe Vehicle

Fail/Hazardous

Licence Number CRR435 Prov. MB NSC # M5800790 Odometer Reading 761329 Odom. Type km mi

Vehicle Identification Number 34SDZTZR1PN112664 Make IHC Model LTGS Year 23 Unit # 320

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR 89500 KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach B

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type
X		3A-4(f) Brake Chamber
X		3A-16(g) 5 Cam Drum Brake System
X		Section 4 - Steering: Defects (if any)
X	X	Section 5 - Instruments & Auxiliary Equipment: Defects (if any) 5-3(c) Horn
X		5-6(a) Windshield Wiper & Washer
X		Section 6 - Lamps: Defects (if any)
X	X	Section 7 - Electrical System: Defects (if any) 7-1(c) Wiring
X	X	7-3(h) Trailer Cord
X	X	Section 8 - Body: Defects (if any) 8-6(a) Rear View Mirror
X	X	8-24(a) Aerodynamic Device
X	X	Section 9 - Tire & Wheel: Defects (if any) 9-4(a) Tire Inflation Pressure
X		Section 10 - Coupling Devices: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	12	13	12	13	100	100	100	100
2	13	13	12	13	80	80	80	80
3	18	18	17	18	90	90	90	90
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date: