

Equipment Pre-delivery Report

Customer: _____ Stock No: CE 2070 Date: 24/03/25
 Make: BELL B45E Serial: 206074 Hours: 10408
 Service Type: ☐ 250hr ☐ 500hr ☒ 1,000hr ☐ 2,000hr ☐ Other



* cross out any items that are not applicable

Item	OK	Comments / Actions Required
1.00	Powertrain	
1.01	Engine: oil level checked <u>Sm</u>	<u>CHANGED ENGINE OIL & FILTER</u>
1.02	Engine: check for oil and/or fuel leaks <u>m</u>	
1.03	Engine: Air filters clean <u>c m</u>	<u>REPLACED ALL AIR FILTERS</u>
1.04	Radiator: condition of hoses, no leaks <u>m</u>	
1.05	Trans/Torque Conv: operational check <u>c m</u>	
1.06	Trans/Torque Conv: oil levels checked <u>Sm</u>	<u>REPLACED FILTERS</u>
1.07	Hydraulic: oil level checked <u>m</u>	<u>REPLACED FILTERS</u>
1.18	Hydraulic: hoses & pipes checked <u>c m</u>	
1.19	Diff/Final Drive: oil level checked <u>c m</u>	<u>CHANGED AXLE & FINAL DR OIL</u>
1.10	Diff/Final Drive: check for leaks	
1.11	Air System: check for leaks <u>c m</u>	
1.12	Main Frame/Chassis: visual check <u>c m</u>	
2.00	Bucket/Blade/Bowl	
2.01	Check linkages (condition ok, greased) <u>Sm</u>	
2.02	Lining condition <u>fm</u>	
2.03	Hydraulics (cylinders, rods, hoses) <u>Sm</u>	
2.04	GET condition <u>/</u>	
3.00	Ripper	
3.01	Check linkages (condition ok, greased) <u>/</u>	
2.02	Hydraulics (cylinders, rods, hoses) <u>/</u>	
2.03	GET condition <u>/</u>	
4.00	Steering/Articulation	
4.01	Steering cylinders <u>c m</u>	
4.02	Hydraulics (cylinders, hoses, leaks?) <u>c m</u>	
4.03	Pins & bushes (check for excessive wear) <u>c m</u>	

Item	OK	!	Comments / Actions Required
5.00 Undercarriage			
5.01 Grousers OK & mounting bolts tight	/		
5.02 Track tension	/		
5.03 Chain condition	/		
5.04 Rollers condition	/		
5.05 Idlers & Sprockets condition	/		
5.06 Track guards secure	/		
6.00 Tyres			
1-2 1-2 1-2 12-34 3-4 5-6 34-56 56-78 Tyre numbering sequence = left to right, and front to back Please circle the correct tyre position appropriate to this machine			
	Serial No.	Tread Depth (mm)	Tyre Pressure (PSI)
POS1	AT2KDD096 YOKO	35	75
POS2	XT7GDD608 YOKO	40	75
POS3	XT7GDD608 YOKO	35	70
POS4	XL7LDC674 YOKO	35	70
POS5	XY1ADD776 YOKO	40	75
POS6	102011J2422 GOOD	20	75
Rim No. HT8KDD4SS			
Comments:			
7.00 Cab			
7.01 Interior clean	Sm		
7.02 First aid kit provided	X		
7.03 Seat inspected & compliant (including seat belts & seat cover)	Sm		
7.04 Operators manual supplied			
7.05 UHF fitted & operational	Sm		Make/Model:
7.06 Gauges, Indicators, & Alarms	Sm		
7.07 Wipers & washers operational	Sm		
7.08 Service brake & park brake operation	Sm		
7.09 A/C operating correctly (heat & cool)	Sm		
7.10 ROPS / FOPS	Sm		
8.00 Other			
8.01 External clean	Sm		
8.02 Fire Extinguisher compliant	Sm		Tag Date: 03/25
8.03 Fire Suppression compliant	N/A		Tag Date: /
8.04 Flashing light fitted & operational	Sm		
8.05 Reverse alarm operational	Sm		
8.06 Lights & Indicators operational	Sm		
8.07 Photos taken of machine & filed			



9.00	Attachments (eg: quick hitch, buckets, parts, tools, accessories, etc.)	
	Item	Description/Condition/Comments
9.01		
9.02		
9.03		
9.04		
9.05		
9.06		
9.07		
9.08		
9.09		
9.10		
10.00	Comments / Observations	
10.01		
10.02		
10.03		
10.04		
10.05		
10.06		
10.07		
10.08		
10.09		
10.10		

Inspection Details:		
		
Inspection carried out by	Signature	Date