

EK12-1

# **STONY INSPECTION SERVICES INC.**

21-52211 Range Road 275, Spruce Grove, Alberta T7X 3V1  
(780)963-6820    admin@stonyinspection.ca

Titan Specialized Hauling Ltd.  
Box 7949  
Edson, Alberta T7E 1W2

Attention: Jonny Sweitzer

20 March 2025


Re:    Certification of Manitex telescopic/articulating picker  
Model: 4596T    Serial: 134013  
Year: N/A    Capacity: 45 ton  
Unit: 357  
Stony Inspection Services Job: 57156

Dear Sir/Madame:

An inspection of the structural elements of the above telescopic/articulating picker was completed by Stony Inspection Services, acting under our direction (Stony Inspection Services Job 57156, dated 20 March 2025, copy attached). The inspection was structural only; no load tests or operational tests were performed. In addition to this structural inspection, the owner and operator are responsible for complying with original equipment manufacturer specifications, OH&S regulations, and the applicable CSA Z-150 and/or ASME B30.5 codes with respect to all inspection, maintenance, and operations of the unit.

Based on this inspection, the above unit is considered structurally fit for continued service.

Yours truly,



59847

Gaylene D. K. Layden, P.Eng.  
Stony Engineering Inc.

<b>PERMIT TO PRACTICE STONY ENGINEERING INC.</b>	
RM SIGNATURE:	<i>G. Layden</i>
RM APEGA ID #:	59847
DATE:	2025-03-21
<b>PERMIT NUMBER: P014039</b> The Association of Professional Engineers and Geoscientists of Alberta (APEGA)	

Association of Professional Engineers & Geoscientists of Saskatchewan		
CERTIFICATE OF AUTHORIZATION Stony Engineering Inc. Number 39856		
Permission to Consult held by:		
Discipline	Sk. Reg. No.	Signature
	21061	<i>G. Layden</i>

