


268 Clearview Drive
Red Deer County, AB T4E 0A1
Tel: 403-340-2225
Email: admin@iconenergyservices.ca



E225-1

June 16, 2025

MCJ Picker Services Inc.
9 Lakes Close
Lacombe, AB, T4L 1S5

ANNUAL CERTIFICATION – STRUCTURAL INSPECTION

Equipment	Telescopic Crane	Job/Report #	DH-4173
Make	Manitex	Inspection Date	June 16, 2025
Model	38124	Inspection Due	June 16, 2026
Serial Number	86352	Unit#	710
Capacity	30 TON		
Inspector Name (NDT)	Devon Hoffensetz		
Applicable Notes			

Icon Energy Services Ltd's technical staff performed visual and non-destructive examination of accessible structural load bearing components on the aforementioned equipment in accordance with Icon Energy Services Ltd's procedures, industry standard practices, and/or OEM recommendations as applicable. Upon final inspection of the equipment and any repairs recommended or performed, no unacceptable defects were noted.

Based on the results of our final inspection and assessment, it is our opinion that the aforementioned equipment is structurally safe for use with regular inspections as per the standards and regulations below as applicable.

Note: BC OHSR Regulations require an additional mechanical and control certification not covered by this certification document.

This Certification is Valid for 1 Year

Applicable Codes (Current Ed)

CSA Z150 – Safety Code on Mobile Cranes

CSA Z150.3 – Safety Code on Articulating Boom Cranes

Occupational Health and Safety Code (Alberta) – Part 6

Occupational Health and Safety Regulation (OHSR - British Columbia) – Section 14

Occupational Health and Safety Regulation (OHSR - Saskatchewan) – Section XIII

Certifying Engineer and Responsible Member
APEGA PERMIT# P11646/ APEGS# 41615/ EGBC# 1002985



Date

June 16, 2025

Doc#	Rev.	Doc Name
ENG-0511-00	1	Annual Mobile Crane Certification