

Owner Code/Schedule Number(s): EX46-3

## RESIDUE LAST CONTAINED

Company: RBS Bulk Systems

Consignor Name: RBS Bulk Systems

Address: 123-55202 825 HWY, Sturgeon County, AB T8L 5C1

Phone Number: 780-720-7906

Transporter: RBS BULK SYSTEMS

Description of tank (including serial number): Superior Commercial Trailer  
2S9BTP532WC031092

Tank emptied/cleaned:

YES

☒

NO

☐

\*please note all tanks must be emptied\*

Tank purge/steamed:

YES

☒

NO

☐

3<sup>rd</sup> Party Certificate provided:

YES

☒

NO

☐

Last Contained:

WATER

☐

SAND

☐

DIESEL

☐

GASOLINE:

☐

Other:

BUTANE

Consignor Signature:

Alex Carter

Date:

AUG. 25/25

Consignor Print Name:

ALEX CARTER

INTERNAL USE ONLY

OK'D BY:

\_\_\_\_\_

EX46-3

**ADVANCE  
TANK CENTRES**

Date: Aug 01/25  
Customer: RBS Unit# 487821  
Work Order No.: ATC 672644001 Serial No.: W092 / 31092  
Employee Name: B. ROWLEY Clock #: 2401

On this date, Advance Tank Centres rendered this tank safe.

It is important to recognize that:

- In order to do so, it may have been necessary to steam or otherwise introduce water in the tank, it's pipeline and other accessories.
- There is a danger of damage to the tank or its equipment through freezing. It is your responsibility to take precautions to avoid such damage. Advance specifically disclaims any liability for damage of this sort.
- As part of the process, pipelines may be left unconnected. Manholes and other devices may also be left on and these must be identified and dealt with. This is your responsibility.
- Prior to being placed back into service all piping connections, valves etc. should be checked and the system should be purged to remove moisture or other contaminants introduced during the steaming or repair operations.
- While this tank was rendered safe on this date is no assurance that it will remain so. It is very important to recognize that this tank may re-gas or otherwise become dangerous at any time and without additional hazardous material being added to the tank. This tank must be retested for safety before any operations are carried out on it or before and after it is moved into a hazardous environment. This would include a shop. This retesting is responsibility; Advance specially disclaims any liability for and future dealings with this tank once it has left our control.

Read and understood this 25<sup>th</sup> day of Aug, 2025.

Signed

Alex Carter

(Print Name)

On behalf of RBS Bulk Systems

Customer Name

Owner Code/Schedule Number(s): EX46-4

## RESIDUE LAST CONTAINED

Company: RBS Bulk Systems

Consignor Name: RBS Bulk Systems

Address: 123-55202 825 HWY, Sturgeon County, AB T8L 5C1

Phone Number: 780-720-7906

Transporter: RBS BULK SYSTEMS

Description of tank (including serial number): Superior Commercial Trailer  
2S9BTP423WC031093

Tank emptied/cleaned: YES ☒ NO ☐


\*please note all tanks must be emptied\*

Tank purge/steamed: YES ☒ NO ☐

3<sup>rd</sup> Party Certificate provided: YES ☒ NO ☐

Last Contained: WATER ☐ SAND ☐ DIESEL ☐ GASOLINE: ☐

Other: BUTANE

Consignor Signature:  Date: AUG. 23/23

Consignor Print Name: ALEX CARTER

INTERNAL USE ONLY

OK'D BY: \_\_\_\_\_

EX46-4



**ADVANCE  
TANK CENTRES**


Date: Aug 01/25  
Customer: RBS Unit#: 487822  
Work Order No.: ATC672645001 Serial No.: W093 / 31093  
Employee Name: B. ROWLEY Clock #: 2401

On this date, Advance Tank Centres rendered this tank safe.

It is important to recognize that:

- In order to do so, it may have been necessary to steam or otherwise introduce water in the tank, its pipeline and other accessories.
- There is a danger of damage to the tank or its equipment through freezing. It is your responsibility to take precautions to avoid such damage. Advance specifically disclaims any liability for damage of this sort.
- As part of the process, pipelines may be left unconnected. Manholes and other devices may also be open and these must be identified and dealt with. This is your responsibility.
- Prior to being placed back into service all piping connections, valves etc. should be checked and the system should be purged to remove moisture or other contaminants introduced during the steaming or repair operations.
- While this tank was rendered safe on this date is no assurance that it will remain so. It is very important to recognize that this tank may re-gas or otherwise become dangerous at any time and without additional hazardous material being added to the tank. This tank must be retested for safety before any operations are carried out on it or before and after it is moved into a hazardous environment. This would include a shop. This retesting is responsibility; Advance specially disclaims any liability for and future dealings with this tank once it has left our control.

Read and understood this 25<sup>TH</sup> day of Aug., 2025.

Signed 

Alex CARTER

(Print Name)

On behalf of RBS BULK SYSTEMS

Customer Name