



## **2021 CMI 175 Mulcher**

**CMI 175CU203103**

This Unit is new, the hour meter has not recorded to previous use, it should show approximately 14 days of work and winter idle.

The engine has been replaced due to operator error, left idle low in winter.

New engine purchased at WAJAX, Edmonton, hours in new engine shows 5.7 hrs. which is correct.

Any Questions, please call - 587-590-2510