



Commercial Vehicle Inspection Report

Decal Number: GP06173
Decal Expiry Date: 2027-Jan-31
Inspection Number: 21850684

Inspection Result:
PASS

FACILITY:	Inland Truck & Equipment Ltd / S20211	INSP. TYPE:	Complete	INSP. START:	2026-Jul-16 08:15 AM MDT
INSPECTOR:	Meyer, Jeremy Kyle / 202685	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Jul-16 10:15 AM MDT
WORK ORDER #:	850	INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	11732077	VIN:	5KKHAXDV0GPHC1240
PLATE #:	KD0108	UNIT/FLEET#:		OWNER/LESSEE NAME:	SALVADOR READY MIX CONCRETE, SALVADOR READY MIX CONCRETE
LICENCED GVW(kg):	54100	BODY STYLE:	Dump Truck	ADDRESS:	17474 56 Ave
VEHICLE YEAR:	2016	ODOMETER:	111714 KM		Surrey, British Columbia
MAKE:	WESTERN ST	HUB ODOMETER:			V3S 1C3, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	28	28
2	Clamp	30L	Automatic	36	36
3	Clamp	30L	Automatic	36	36

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
18			18	✓
12	12	12	12	
15	15	15	15	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	32	29
2	28	26
3	24	26

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	19	19
Lining (Shoe)	19	19
Lining (Shoe)	19	19

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Inspector: Meyer, Jeremy Kyle

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Jul-17 08:16 AM MDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

7/17/2026 8:16:33 AM MDT

A12-26