



**BRITISH
COLUMBIA**

Commercial Vehicle Inspection Report

Decal Number: GJ68020
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21458340

Inspection Result:
PASS

FACILITY:	BABINE TRUCK & EQUIPMENT LTD. / S20039	INSP. TYPE:	Complete	INSP. START:	2025-Aug-04 12:05 PM PDT
INSPECTOR:	JITHIN RAJ, N/A / 300419	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Aug-13 09:10 AM PDT
WORK ORDER #:	317611	INSP. REASON:	Semi-annual		

VEHICLE JUR:	British Columbia	REGI:	03827085	VIN:	2FZHATDJ07AX85344
PLATE #:	VP6873	UNIT/FLEET#:	VT03	OWNER/LESSEE NAME:	STOREY'S, STOREY'S EXCAVATING LTD
LICENCED GVW(kg):	29937	BODY STYLE:	Pumper Truck	ADDRESS:	507 11TH AVE E
VEHICLE YEAR:	2007	ODOMETER:	221508 KM		Prince Rupert, British Columbia
MAKE:	STERLING	HUB ODOMETER:			V8J2W6, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Repaired (same day)	LOOSE SHOCK SECURED.
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	PLATE LAMP AND ROOF LAMP REPLACED.
Section 7 - Electrical System	Repaired (same day)	BACK UP ALARM REPLACED.
Section 8 - Frame and Body	Repaired (same day)	CROSS MEMBER BEHIND TRANSMISSION REPLACED.
Section 9A - Tires	Passed	
Section 9B - Wheels	Repaired (same day)	2L, 2R WHEEL SEAL REPLACED.
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Stack Adj.	Left	Right	Tire Tread Depth (mm)					
						Outer L	Inner L	Inner R	Outer R	Steering	
1	Clamp	24	Automatic	30	30	9			8	✓	
2	Clamp	30L	Automatic	37	36	20	15	20	20		
3	Clamp	30L	Automatic	35	36	20	20	15	15		

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	30	40
2	45	45
3	55	55

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	18	18
Lining (Shoe)	18	18
Lining (Shoe)	18	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: JITHIN RAJ, N/A

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Aug-13 09:11 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

8/13/2025 9:11:05 AM PDT

AKG-1