



Commercial Vehicle Inspection Report

Decal Number: GM71177
Decal Expiry Date: 2026-Aug-31
Inspection Number: 21679333

Inspection Result:
PASS

FACILITY:	OCEAN TIRE SERVICE LTD. / S20280	INSP. TYPE:	Complete	INSP. START:	2026-Feb-26 01:05 PM PST
INSPECTOR:	RAI, SARABDEEP SINGH / 202959	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Feb-26 03:00 PM PST
WORK ORDER #:		INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	13585639	VIN:	3AKJHHDV5NSMV7570
PLATE #:	84303P	UNIT/FLEET#:	2029	OWNER/LESSEE NAME:	C.SANGHERA TRANSPORT, LTD.
LICENCED GVW(kg):	40000	BODY STYLE:	Truck Tractor	ADDRESS:	110-6638 152A ST Surrey, British Columbia
VEHICLE YEAR:	2022	ODOMETER:	743423 Miles		V3S7J1, Canada
MAKE:	FREIGHTLIN	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) AXLE 3 R/S BRAKE INSTALL AND SECURE TRAILER HOSES
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) R/S FOG LAMP INSTALL
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Automatic	34	35	10			9	✓
2	Clamp	30L	Automatic	34	35	16	14	15	16	
3	Clamp	30L	Automatic	33	34	16	15	15	16	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	45	45
2	75	75
3	65	30

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	16
Lining (Shoe)	14	13
Lining (Shoe)	13	21

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: RAI, SARABDEEP SINGH

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Feb-27 05:43 PM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NS/CVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

2/27/2026 5:43:36 PM PST

D09-1