



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GN86722
Decal Expiry Date: 2027-Jun-30
Inspection Number: 21828760

Inspection Result:

PASS

CITY: OCEAN TIRE SERVICE LTD. / S20280 INSP. TYPE: Complete INSP. START: 2026-Jun-28 09:00 AM PDT
INSPECTOR: RAI, SARABDEEP SINGH / 202959 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2026-Jun-28 10:30 AM PDT
WORK ORDER #:

VEHICLE JUR: British Columbia REGI: 11474329 VIN: 1UYVS2533GG455412
PLATE #: 12724J UNIT/FLEET#: v5324 OWNER/LESSEE NAME: C.SANGHERA TRANSPORT, LTD.
LICENCED GVW(kg): 999999 BODY STYLE: Van Trailer ADDRESS: 110-6638 152 A STREET
VEHICLE YEAR: 2016 ODOMETER: Surrey, British Columbia
MAKE: UTILITY HUB ODOMETER: V3S5X5, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) AXLE 1 AND 2 BOTH SIDE , SLAG ADJUSTER INSTALL , AXLE 2 LEFT SIDE AND AXLE 1 RIGHT INSTALL NEW PIGGY BAG , BOTH GLAD HANDS REPLACED
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Repaired (same day) ABS ISSUE FIXED
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	35	36
2	Clamp	30	Automatic	34	35

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
11	11	11	11	
4	4	4	5	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	45	45
2	45	45

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	18	17
Lining (Shoe)	17	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: RAI, SARABDEEP SINGH Signature:

This Inspection Report was submitted to CVSE on 2026-Jun-28 02:15 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

DO9-2

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSED014

6/28/2026 2:24:06 PM PDT