

Commercial Vehicle **Inspection Report**

Decal Number: Decal Expiry Date: Inspection Number:

GH21732 2026-Feb-28 21237810

Inspection Result:

INSP. TYPE: FACILITY: CULLEN DIESEL POWER LTD. / 2025-Feb-13 02:30 AM PST Complete INSP START INSP. CLASS: Class 2 - Heavy Vehicle with LGVW INSP. COMPLETE: 2025-Feb-14 07:59 AM PST INSPECTOR: DISHKIN, MICHAEL ROBERT / 5501 kg or more 105875 INSP. REASON: **Annual** WORK ORDER #: R160005871 **VEHICLE JUR:** British Columbia REGI: 11852289 VIN: 1FDUF5GY7GEB08648 PLATE #: KP9348 UNIT/FLEET#: G1015 OWNER/LESSEE NAME: TELUS COMMUNICATION INC. TELUS LICENCED GVW(kg): 9300 BODY STYLE: ADDRESS: **Utility Truck** 11778 224 ST VEHICLE YEAR: 2016 ODOMETER: 95493 KM Maple Ridge, British Columbia MAKE: FORD HUB ODOMETER: V2X6A6, Canada MODEL: BRAKE TYPE: Hydraulic FUEL TYPE: Gasoline Vehicle Identification (VIN) Passed Section 1 - Power Train Passed Section 2 - Suspension Passed Section 3 - Brake System Passed Section 3H - Hydraulic Brakes Passad Section 4 - Steering Passed Section 5 - Instruments and Auxiliary Passed Equipment Section 6 - Lamps REAR ID LIGHT OUT Repaired (same day) Section 7 - Electrical System Passed Section 8 - Frame and Body Passed Section 9A - Tires Passed Section 9B - Wheels **Passed** Section 10 - Coupling Devices Passed Section 11 - Other Vehicle Components Not Applicable Tire Tread Depth (mm) Brake Lining/Pad (mm) Rotor Thickness or Drum Inside Diameter (mm) Lining/Pad Right Axles Outer L Inner L Inner R Outer R Steering Left Right Rotor/Drum Left 39.40 39.90 1 8 Pad 12 12 Rotor 39.10 39.20 13 Rotor 2 13 Pad 13

Inspection Comments:

Comment:

Has this Vehicle been road tested? No DISHKIN, MICHAEL ROBERT Inspector:

Road Test Date:

Comment:

Signature:

Road Tester:

Comment:

This Inspection Report was submitted to CVSE on 2025-Feb-14 07:59 AM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.