



# Commercial Vehicle Inspection Report

Decal Number: GB60879  
Decal Expiry Date: 2025-Jun-30  
Inspection Number: 20960883

Inspection Result:  
**PASS**

FACILITY: OK TIRE DILWORTH / S16983 INSP. TYPE: Complete INSP. START: 2024-Jun-07 11:48 AM PDT  
INSPECTOR: Dankoski, Robert David / 203342 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more INSP. COMPLETE: 2024-Jun-07 12:48 PM PDT  
WORK ORDER #: 21624 INSP. REASON: Annual

VEHICLE JUR: British Columbia REGI: 13566728 VIN: 1GDE5E3967F420279  
PLATE #: SS1143 UNIT/FLEET#: OWNER/LESSEE NAME: MASON, BRYCE  
LICENCED GVW(kg): 8895 BODY STYLE: Flat Deck ADDRESS: 2154 CRESTVIEW CRESCENT, 2154 CRESTVIEW CRESCENT  
VEHICLE YEAR: 2007 ODOMETER: 346722 KM Castlegar, British Columbia  
MAKE: GMC HUB ODOMETER: V1N3B3, Canada  
MODEL: BRAKE TYPE: Hydraulic  
FUEL TYPE: Diesel

|   |                |
|---|----------------|
| Vehicle Identification (VIN)                    | Passed         |
| Section 1 - Power Train                         | Passed         |
| Section 2 - Suspension                          | Passed         |
| Section 3 - Brake System                        | Passed         |
| Section 3H - Hydraulic Brakes                   | Passed         |
| Section 4 - Steering                            | Passed         |
| Section 5 - Instruments and Auxiliary Equipment | Passed         |
| Section 6 - Lamps                               | Passed         |
| Section 7 - Electrical System                   | Passed         |
| Section 8 - Frame and Body                      | Passed         |
| Section 9A - Tires                              | Passed         |
| Section 9B - Wheels                             | Passed         |
| Section 10 - Coupling Devices                   | Passed         |
| Section 11 - Other Vehicle Components           | Not Applicable |

| Tire Tread Depth (mm) |         |         |         |         | Brake Lining/Pad (mm) |            |      | Rotor Thickness or Drum Inside Diameter (mm) |            |       |       |
|-----------------------|---------|---------|---------|---------|-----------------------|------------|------|--|------------|-------|-------|
| Axes                  | Outer L | Inner L | Inner R | Outer R | Steering              | Lining/Pad | Left | Right  | Rotor/Drum | Left  | Right |
| 1                     | 19.8    |         |         | 19.8    | ✓                     | Pad        | 14   | 14   | Rotor      | 38.00 | 38.00 |
| 2                     | 19.8    | 19.8    | 19.8    | 19.3    |                       | Pad        | 10   | 10   | Rotor      | 38.00 | 38.00 |
| Comment:              |         |         |         |         | Comment:              |            |      | Comment:                                     |            |       |       |

Inspection Comments:  
Has this Vehicle been road tested? Yes Road Test Date: Before Inspection Road Tester: ROBERT DANKOSKI  
Inspector: Dankoski, Robert David Signature:

This Inspection Report was submitted to CVSE on 2024-Jun-07 12:49 PM PDT  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

6/7/2024 12:51:02 PM PDT