

## Commercial Vehicle Inspection Report

Decal Number: **Decal Expiry Date:** 

Inspection Number:

GK84493 2026-Oct-31 21521684

Inspection Result:

FACILITY:

BR & STRUCK & TRAILER

INSP. TYPE:

INSP. CLASS:

Complete

Class 3 - Trailer and Semi-Trailer

INSP. START:

INSP. COMPLETE:

2025-Oct-03 12:16 PM PDT

**NORK ORDER #:** 

NSPECTOR:

REPAIR / S15610

Plaha, Ranjit Singh / 111736

INSP. REASON:

Annual

11357353

2025-Oct-04 07:35 AM PDT

/EHICLE JUR:

British Columbia

PLATE #:

JCENCED GVW(kg): 999999 2015

/EHICLE YEAR: MAKE.

MANAC

WODEL:

REGI:

UNIT/FLEET#:

582 SD

Air

BODY STYLE: Flat Deck Traffe ODOMETER:

HUB ODOMETER: BRAKE TYPE:

FUEL TYPE:

VIN:

OWNER/LESSEE NAME:

ADDRESS:

2M5131610F1148226

eternity transport ltd, eternity transport

19966 wharf st, 19966 wharf st Maple Ridge, British Columbia

v2x1a1, Canada

Vehicle Identification (VIN)

Section 1 - Power Train Section 2 - Suspension Section 3 - Brake System

Section 3A - Air Brakes Section 3H - Hydraulic Brakes Section 4 - Steering

Section 5 - Instruments and Auxiliary

Equipment

Section 6 - Lamps Section 7 - Electrical System Section 8 - Frame and Body

Section 9A-Tires Section 9B - Wheels Section 10 - Coupling Devices Section 11 - Other Vehicle Components

Passed

Not Applicable Passed

Passed Passed Not Applicable Not Applicable

Not Applicable

Passed Passed Passed Passed Passed

Passed Not Applicable

Air Brake Chamber Type, Size and Push Rod	Stroke	(mm)
---	--------	------

			()			o mode bobt	()			
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	33	33	8	8	8	8	
2	Clamp	30	Automatic	33	33	6	6	6	6	
3	Clamp	30	Automatic	33	33	8	8	7	7	
Comment:						Comment:				

Tire Tread Depth (mm)

Road Tester:

Air Brake Camshaft	Rotation (degree	es)
Axles	Left	Right
1	42	48
2	40	40
3	50	50

Brake	Lining/
	Linin
	Lining
	Lining
	Lining
Comr	nent:

.ining/Pad (mm)		
Lining/Pad	Left	Right
Lining (Shoe)	18	18
Lining (Shoe)	18	18
Lining (Shoe)	16	16
12.29		

Drum	
Drum	
omment: Air Brake Camshaft Rotation performed. R	lotor
nickness or Drum Diameter not measured.	

Left

Right

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum

Drum

nspection Comments:

Comment:

las this Vehicle been road tested? Plaha, Ranjit Singh nspector:

Road Test Date: No Signature:

This Inspection Report was submitted to CVSE on 2025-Oct-04 02:23 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carners, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this nformation, you may contact the Sr. Manager, NSCIVIP at the Commercial Vehicle Safety Enforcement

>VSE0014

10/4/2025 2:23:58 PM PDT