



# Commercial Vehicle Inspection Report

Decal Number: GJ23759  
 Decal Expiry Date: 2026-Apr-30  
 Inspection Number: 21308929

A05-11  
 Inspection Result:  
**PASS**

**FACILITY:** DELTA TRUCK REPAIR (1991) / S3359  
**INSPECTOR:** FRANSEN, GARY DAVID / 105639  
**WORK ORDER #:** 130752  
**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 3 - Trailer and Semi-Trailer  
**INSP. REASON:** Annual  
**INSP. START:** 2025-Apr-09 01:00 PM PDT  
**INSP. COMPLETE:** 2025-Apr-11 10:16 AM PDT

**VEHICLE JUR:** British Columbia  
**PLATE #:** 81068W  
**LICENCED GVW(kg):** 999999  
**VEHICLE YEAR:** 2000  
**MAKE:** THRUWAY  
**MODEL:**  
**REGI:** 00053660  
**UNIT/FLEET#:** 28RF11  
**BODY STYLE:** Flat Deck Trailer  
**ODOMETER:**  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**  
**VIN:** 2T9FA2824Y1011554  
**OWNER/LESSEE NAME:** COMOX VALLEY DISTRIBUTION LTD, COMOX VALLEY DISTRIBUTION LTD  
**ADDRESS:** 11398 BRIDGEVIEW DRIVE, Surrey, British Columbia V3R0C2, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Repaired (same day) REPLACED 7-WIRE PLUG
Section 8 - Frame and Body	Passed with Caution FRAME/CROSSMEMBERS RUSTY
Section 9A - Tires	Passed
Section 9B - Wheels	Repaired (same day) REPLACED LEFT HUB CAP #1 AXLE
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axes	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	38	40	8	6	10	11	
2	Clamp	30	Automatic	40	40	8	8	9	9	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)				Rotor Thickness or Drum inside Diameter (mm)			
Axes	Left	Right	Lining/Pad		Left	Right	Rotor/Drum		Left	Right
1	60	60	Lining (Shoe)		15	15	Drum		0.00	0.00
2	45	40	Lining (Shoe)		17	18	Drum		0.00	0.00
Comment:			Comment:				Comment: DRUMS NOT REMOVED			

**Inspection Comments:**  
 Has this Vehicle been road tested?  No **Road Test Date:** \_\_\_\_\_ **Road Tester:** \_\_\_\_\_  
**Inspector:** FRANSEN, GARY DAVID **Signature:** \_\_\_\_\_

This inspection Report was submitted to CVSE on 2025-Apr-11 10:16 AM PDT  
 The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION**  
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the St. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement  
 CVSE014  
 4/11/2025 10:16:28 AM PDT