

A05-15



Commercial Vehicle Inspection Report

Decal Number: GL01896
Decal Expiry Date: 2026-Jun-30
Inspection Number: 21589883

Inspection Result:
PASS

FACILITY: MACK SALES & SERVICE / S5774	INSP. TYPE: Complete	INSP. START: 2025-Dec-02 12:00 PM PST
INSPECTOR: MOSSA, ROBERT ANTHONY / 301538	INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE: 2025-Dec-02 01:30 PM PST
WORK ORDER #: 399768	INSP. REASON: Semi-annual	

VEHICLE JUR: British Columbia	REGI: 10406797	VIN: 1M1AW07Y0CM020471
PLATE #: SY0522	UNIT/FLEET#: 336	OWNER/LESSEE NAME: COMOX VALLEY DISTRIBUTION LTD.,
LICENCED GVW(kg): 63500	BODY STYLE: Truck Tractor	ADDRESS: 11398 BRIDGEVIEW DRIVE
VEHICLE YEAR: 2012	ODOMETER: 757114 KM	Surrey, British Columbia
MAKE: MACK	HUB ODOMETER:	V3R 0C2, Canada
MODEL:	BRAKE TYPE: Air	
	FUEL TYPE:	

Vehicle Identification (VIN)	Result	Notes
Section 1 - Power Train	Repaired (same day)	U-JOINT AND YOKE REPLACED @ STEADY BEARING
Section 2 - Suspension	Repaired (same day)	FRONT LEFT AND RIGHT SPRING PINS AND BUSHINGS REPLACED, U-BOLTS ON SECOND AXLE RIGHT SIDE REPLACED
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	BOTH GLAD HAND SEALS REPLACED
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Repaired (same day)	DRAG-LINK REPLACED
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Repaired (same day)	5TH WHEEL BUSHINGS REPLACED
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	35	30	9			5	✓
2	Clamp	30	Automatic	50	50	16	16	17	17	
3	Clamp	30	Automatic	45	45	16	15	15	15	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	40	35	Lining (Shoe)	17	18	Drum		
2	35	35	Lining (Shoe)	18	18	Drum		
3	37	32	Lining (Shoe)	17	18	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:
 Has this Vehicle been road tested? No
 Inspector: MOSSA, ROBERT ANTHONY
 Road Test Date: _____ Road Tester: _____
 Signature:

This Inspection Report was submitted to CVSE on 2025-Dec-02 02:31 PM PST
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement
 CVSE0014
 12/2/2025 2:31:06 PM PST