



Commercial Vehicle Inspection Report

Decal Number: GD96900
Decal Expiry Date: 2026-Jan-31
Inspection Number: 21222812

Inspection Result:
PASS

A05-

FACILITY:	PACIFIC CROSSROAD INDUSTRIAL REPAIRS / S17080	INSP. TYPE:	Complete	INSP. START:	2025-Jan-30 07:37 AM PST
INSPECTOR:	BERNSTEIN, RALPH HERBERT / 106846	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2025-Jan-30 09:38 AM PST
WORK ORDER #:	7043	INSP. REASON:	Annual		

VEHICLE JUR:	British Columbia	REGI:	03828935	VIN:	1DTV61Z20XA275796
PLATE #:	08348K	UNIT/FLEET#:	210	OWNER/LESSEE NAME:	COMOX VALLEY DISTRIBUTION LTD., .
LICENCED GVW(kg):	999999	BODY STYLE:	Reefer Van Trailer	ADDRESS:	11398 BRIDGEVIEW DRIVE
VEHICLE YEAR:	1999	ODOMETER:			Surrey, British Columbia
MAKE:	DORSEY	HUB ODOMETER:			V3R0C2, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxillary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) REPAIR 3 UPPER SIDE CLEARANCE LIGHTS 1 VERY DIM NEW ONE ON ORDER
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	35	38	15	15	14	15	
2	Clamp	30	Automatic	37	39	5	10	11.5	9	
3	Clamp	30	Automatic	38	35	16	17	12	7	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	41	52	Lining (Shoe)	16	16	Drum		
2	43	53	Lining (Shoe)	19	16	Drum		
3	66	45	Lining (Shoe)	11	19	Drum		
Comment:			Comment: L2 AND R3 NEW LINING			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:
 Has this Vehicle been road tested? No Road Test Date: _____ Road Tester: _____
 Inspector: BERNSTEIN, RALPH HERBERT Signature: *R. Bernstein*

This Inspection Report was submitted to CVSE on 2025-Jan-30 11:50 AM PST
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VP at the Commercial Vehicle Safety Enforcement