

Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date: Inspection Number: FX43993 2024-Aug-31 20622340

Inspection Result: **PASS**

FACILITY:

Complete

INSP. START:

2023-Aug-18 01:30 PM PDT

COJAX HEAVY DUTY REPAIR LTD. / S6814

INSP. CLASS: INSP. REASON: Class 3 - Trailer and Semi-Trailer

INSP. COMPLETE:

INSPECTOR:

CLIFFORD, JOSEPH RODERICK /

Annual

2023-Aug-18 02:30 PM PDT

WORK ORDER #:

VEHICLE JUR:

115150 17367

British Columbia

24627U

LICENCED GVW(kg): 999999 2012 VEHICLE YEAR: MAKE:

REGI: UNIT/FLEET#:

K135B BODY STYLE: ODOMETER:

Flat Deck Trailer

11785739

OWNER/LESSEE NAME: ADDRESS:

2M5120850C1128549 KINGSLEY TRUCKING LTD, .

PO BOX 512

Coombs, British Columbia

V0R1M0, Canada

MODEL:

PLATE #:

MANAC

HUB ODOMETER: BRAKE TYPE: FUEL TYPE:

Air

Passed Vehicle Identification (VIN) Not Applicable Section 1 - Power Train Passed Section 2 - Suspension Not Applicable

Section 3 - Brake System Passed Section 3A- Air Brakes Section 3H - Hydraulic Brakes Section 4 - Steering

Section 5 - Instruments and Auxiliary Equipment Section 6 - Lamps

Section 7 - Electrical System Section 8 - Frame and Body Section 9A-Tires Section 9B - Wheels Section 10 - Coupling Devices Section 11 - Other Vehicle Components

Not Applicable Not Applicable Not Applicable Passed

Passed Passed Passed Passed Passed Not Applicable

Left

60

50

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	33	30
2	Clamp	30	Automatic	37	38

Right

25

75

	Comment:		
rake Lining/Pad (mm)			
Lining/Pad	Left	. F	Right

Lining (Shoe) 15 21 Lining (Shoe) 16 15 Comment:

Rotor Thickness or Drum Inside Diameter (mm) Rotor/Drum Left

Outer R

10

11

Drum Drum

Inner R

10 11

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Axles

1

2

Comment:

Has this Vehicle been road tested? Inspector: CLIFFORD, JOSEPH RODERICK

Air Brake Camshaft Rotation (degrees)

Road Test Date:

Signature:

Road Tester:

Inner L

15

Tire Tread Depth (mm)

Outer L

14

This Inspection Report was submitted to CVSE on 2023-Aug-18 03:59 PM PDT

This inspection report was summand to CVDE on 2020-yag- to 00:00 FMFD1.

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

NOTICE REP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal formation collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities), if you have any questions about the collection of this CAUSED 14.

Steering