



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: FX43992
Decal Expiry Date: 2024-Aug-31
Inspection Number: 20622311

Inspection Result:

PASS

FACILITY: COJAX HEAVY DUTY REPAIR LTD. / S6814
INSPECTOR: CLIFFORD, JOSEPH RODERICK / 115150
WORK ORDER #: 17367
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2023-Aug-18 11:05 AM PDT
INSP. COMPLETE: 2023-Aug-18 01:15 PM PDT

VEHICLE JUR: British Columbia
PLATE #: 24626U
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2012
MAKE: MANAC
MODEL:
REGI: 11785193
UNIT/FLEET#: K135A
BODY STYLE: Flat Deck Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
VIN: 2M5130979C1128546
OWNER/LESSEE NAME: KINGSLEY TRUCKING LTD.,
ADDRESS: PO BOX 512
Coombs, British Columbia
V0R1M0, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	33	42	12	12	10	9	
2	Clamp	30	Automatic	36	35	8	10	7	7	
3	Clamp	30	Automatic	27	30	13	13	7	8	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	30	50
2	25	25
3	25	25

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	21	17
Lining (Shoe)	21	21
Lining (Shoe)	21	21

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.


Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: CLIFFORD, JOSEPH RODERICK

Signature: 

This Inspection Report was submitted to CVSE on 2023-Aug-18 03:49 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSO/VIP at the Commercial Vehicle Safety Enforcement

CVSE014

8/18/2023 3:49:33 PM PDT