



# Commercial Vehicle Inspection Report

Decal Number: GH95759  
Decal Expiry Date: 2026-May-31  
Inspection Number: 21564112

Inspection Result:  
**PASS**

408-2

<b>FACILITY:</b>	ATS MECHANICAL INC. / S14200	<b>INSP. TYPE:</b>	Complete	<b>INSP. START:</b>	2025-Nov-12 06:05 AM PST
<b>INSPECTOR:</b>	GRAY, DUSTIN / 201966	<b>INSP. CLASS:</b>	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	<b>INSP. COMPLETE:</b>	2025-Nov-12 08:46 AM PST
<b>WORK ORDER #:</b>		<b>INSP. REASON:</b>	Semi-annual		
<b>VEHICLE JUR:</b>	British Columbia	<b>REGI:</b>	12487240	<b>VIN:</b>	1XPXP49X3JD416327
<b>PLATE #:</b>		<b>UNIT/FLEET#:</b>	25	<b>OWNER/LESSEE NAME:</b>	agri-trans services inc, ats
<b>LICENCED GVW(kg):</b>	63500	<b>BODY STYLE:</b>	Truck Tractor	<b>ADDRESS:</b>	2200 kirtan ave
<b>VEHICLE YEAR:</b>	2018	<b>ODOMETER:</b>	808433 KM		Armstrong, British Columbia
<b>MAKE:</b>	PETERBILT	<b>HUB ODOMETER:</b>			v0e1b0, Canada
<b>MODEL:</b>		<b>BRAKE TYPE:</b>	Air		
		<b>FUEL TYPE:</b>			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) repaired air leak at air dryer
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) replaced license plate light
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Disc	N/A	Not Applicable	0	0	8			9	✓
2	Clamp	24L	Automatic	41.3	38.1	6			12.5	✓
3	Disc	N/A	Not Applicable	0	0	21	21	21	21	
4	Disc	N/A	Not Applicable	0	0	21	21	21	21	
Comment:						Comment:				

# Commercial Vehicle Inspection Report

Decal Number: GH95759  
Decal Expiry Date: 2026-May-31  
Inspection Number: 21564112

Inspection Result:  
**PASS**

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	0	0	Pad	15	16	Rotor	41.30	41.20
2	41	37	Lining (Shoe)	20	20	Drum	419.00	419.00
3	0	0	Pad	21	21	Rotor	39.80	40.50
4	0	0	Pad	14	15	Rotor	39.90	39.10
Comment: drop axle is only drum brake axle			Comment:			Comment:		

## Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: GRAY, DUSTIN

Signature: \_\_\_\_\_

This Inspection Report was submitted to CVSE on 2025-Nov-12 08:47 AM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

11/12/2025 8:48:00 AM PST