



Commercial Vehicle Inspection Report

Docal Number: GJ96449
 Docal Expiry Date: 2026-Jun-30
 Inspection Number: 21388672

Inspection Result:
PASS

FACILITY:	MOGA TRUCK REPAIR LTD / S20362	INSP. TYPE:	Complete	INSP. START:	2025-Jun-11 04:00 PM PDT
INSPECTOR:	BRAR, GAGANDEEP SINGH / 203058	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2025-Jun-11 06:30 PM PDT
WORK ORDER #:	21390	INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REG#:	14353084	VIN:	1UYVS2634R3013611
PLATE #:	56607K	UNIT/FLEET#:	vk130	OWNER/LESSEE NAME:	VK DELIVERY AND MOVING SERVICES, 4-588 ANNANCE CRT
LICENCED GVW(kg):	0	BODY STYLE:	Van Trailer	ADDRESS:	4-588 ANNANCE CRT, 4-588 ANNANCE CRT Delta, British Columbia V3M8Y8, Canada
VEHICLE YEAR:	2024	ODOMETER:			
MAKE:	UTILITY	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	#2 right main diaphragm replaced
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Repaired (same day)	fix abs light
Section 8 - Frame and Body	Repaired (same day)	right mud flap secured
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	#2 right main diaphragm replaced
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Repaired (same day)	fix abs light
Section 8 - Frame and Body	Repaired (same day)	right mud flap secured
Section 9A - Tires	Repaired (same day)	need to replace #1 left tires before next dispatch
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	33	34	4	4	5	5	
2	Clamp	30	Automatic	32	34	11	11	11	11	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	7	875	Lining (Shoe)	14	18	Drum		
2	82	70	Lining (Shoe)	13	14	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:
 Has this Vehicle been road tested? No
 Inspector: BRAR, GAGANDEEP SINGH
 Road Test Date: 
 Signature: _____
 Road Tester: _____

This Inspection Report was submitted to CVSE on 2025-Jun-13 11:06 AM PDT
 The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 210 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing the vehicle inspection and for generally administering the Vehicle Inspection Program and the Inland Safety Code (e.g. regulating certified, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP of the Commercial Vehicle Safety Enforcement.