

Commercial Vehicle Inspection Report

Decal Number: GH25076
Decal Expiry Date: 2025-Jul-31
Inspection Number: 21200739

AI2-31
Inspection Result:
PASS

FACILITY: PENINSULA INDUSTRIAL GROUP LTD. / S20374
INSPECTOR: VAN ADRICHEM, RORY KENNETH / 200774
WORK ORDER #: 2582

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual

INSP. START: 2025-Jan-09 08:51 AM PST
INSP. COMPLETE: 2025-Jan-09 04:43 PM PST

VEHICLE JUR: British Columbia
PLATE #: 05021L
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2013
MAKE: CROSS COUN
MODEL: DUMP

REGI: 10593563
UNIT/FLEET#: TRL17
BODY STYLE: Dump Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 2C9EUR331DM183206
OWNER/LESSEE NAME: D.L. Bins, Ltd.
ADDRESS: 6588 Bryn Rd
Saanichton, British Columbia
V8M 1X6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) Replace LH front marker light
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) Cracks welded at crossmember
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	31	30
2	Clamp	30	Automatic	33	33
3	Clamp	30	Automatic	34	31

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
9	9	4	7	
9	5	6	6	
9	9	8	8	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	65	65
2	35	35
3	35	35

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	15
Lining (Shoe)	20	20
Lining (Shoe)	20	20

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? ☒ No **Road Test Date:** **Road Tester:**
Inspector: VAN ADRICHEM, RORY KENNETH **Signature:**

This Inspection Report was submitted to CVSE on 2025-Jan-09 04:44 PMPST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSED014

1/9/2025 4:44:34 PM PST

