

## **Commercial Vehicle Inspection Report**

**Decal Number: Decal Expiry Date:** 

Inspection Number:

**GD77488** 2025-Oct-31 21118955

FACILITY: SAMMY'S TRUCK & TRAILER / NSPECTOR. Sammy, Vijay Krishna / 106310

INSP. TYPE: INSP. CLASS:

INSP. REASON:

Complete Class 3 - Trailer and Semi-Trailer INSP. START: INSP. COMPLETE: 2024-Oct-24 08:00 AM PDT 2024-Oct-24 09:00 AM PDT

**NORK ORDER #:** /EHICLE JUR:

British Columbia

REGI:

09731899

Van Trailer

Annual

1JJV532F8XF579084

PLATE #:

53741K

UNIT/FLEET#: 53V021

OWNER/LESSEE NAME:

LIBERTY TIRE RECYCLING CANADA. WESTERN RUBBER PRODUCT

JCENCED GVW(kg): 999999

BODY STYLE:

ADDRESS:

969 CLIVEDEN AVE, 969 CLIVEDEN

Delta, British Columbia

/EHICLE YEAR: MAKE:

MODEL:

1999 **FRUEHAUF**  **ODOMETER: HUB ODOMETER:** 

**BRAKE TYPE:** Air

**FUEL TYPE:** 

V3M5R6, Canada

Vehicle Identification (VIN)

Section 1 - Power Train Section 2 - Suspension Section 3 - Brake System Section 3A - Air Brakes

Section 3H - Hydraulic Brakes Section 4 - Steering Section 5 - Instruments and Auxiliary

Equipment Section 6 - Lamps Section 7 - Electrical System Section 8 - Frame and Body

Section 9A - Tires Section 9B - Wheels Section 10 - Coupling Devices Section 11 - Other Vehicle Components Passed

Not Applicable Passed Passed **Passed** Not Applicable Not Applicable

Not Applicable Passed

Passed Passed **Passed** Passed Passed Not Applicable

\ir Brake Chamber Type, Size and Push Rod Stroke (mm)

Type Size Slack Adj. Axies Clamp 30 **Automatic** 1 2 Clamp 30 Automatic Comment:

65

65

Left Right 38 38 38 38

Brake Lining/Pad (mm)

Lining/Pad

Lining (Shoe)

Lining (Shoe)

11 11 Comment:

Left

16

16

Tire Tread Depth (mm)

Outer L

Right 16 16

Rotor Thickness or Drum Inside Diameter (mm) Rotor/Drum Drum

Inner R

11

Left

Steering

Right

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

**Outer R** 

8

8

nspection Comments:

Axles

2

Comment:

las this Vehicle been road tested? Sammy, Vijay Krishna nspector:

\ir Brake Camshaft Rotation (degrees)

No

Right

65

65

Road Test Date:

Comment:

Signature:

Road Tester:

inner L

9

11

his Inspection Report was submitted to CVSE on 2024-Oct-24 03:59 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

he personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this nformation, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement