



# Commercial Vehicle Inspection Report

Decal Number: FW40287  
Decal Expiry Date: 2024-Feb-29  
Inspection Number: 20405392

Inspection Result: PASS

Model: CRAWFORD TRUCK & EQUIPMENT / 85418  
Inspection Type: Inspection Class: Class 3 - Trailer and Semi-Trailer  
Inspection Start Date/Time: 2023-Feb-10 08:09 AM  
Inspection Complete Date/Time: 2023-Feb-10 11:08 AM  
Inspector: CRAWFORD, TREVOR STEVEN / 105268  
Inspection Number: Actual  
Work Order Number: RC06877

Vehicle Jurisdiction: British Columbia  
Registration Number: 097D7888  
VIN: 1LH880U17WLAG879  
Plate Number: 77882U  
Licence #/W (kg): 990999  
Vehicle Year: 1998  
Make: LANDOL  
Brake Type: Air  
Fuel Type: Diesel  
Adapted: No  
Hub Odometer: No  
Body Style: Flat Deck Trailer  
Model: No  
Unit/Fleet Number: No  
Owner/Lessee Name: TROWELER CONCRETE CONTRACTORS, TROWELER CONCRETE CONTRACTORS  
Address: 4380 COLUMBIAN AVE  
City: Trail  
Province/State: British Columbia  
Postal Code/ZIP: V1N3N6  
Country: Canada

Section	Reason	Comments
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed (see 45)	RE/RE AUTO/BLACK
Section 3A - Air Brakes	Passed	
Section 3B - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Not Applicable	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke Measurement (in mm)

Axis (front)	Type	Size	Back Adj.	Left	Right
1	Comp.	30	Automatic	98.1	98.1
2	Comp.	30	Automatic	98.1	98.1

Comments:

Tire Tread Depth (mm)

Axis (front)	Outer L&R	Inner Left	Inner Right	Overall Right	Overall Left?
1	8	8	8	8	
2	12	13	13	13	

Comments:

Air Brake Chamber Position Measurement (degrees)

Axis (front)	Left (degrees)	Right (degrees)
1	48	48
2	98	40

Comments:

Brake Linings/Pads/ Shoes (mm)

Axis (front)	Left/Pad	Left	Right
1	Linings (Shoe)	17	17
2	Linings (Shoe)	18	18

Comments:

Brake Thickness to Drum Inside Diameter Measurement (mm)

Axis (front)	Inner/Drum	Left	Right
1	Drum		
2	Drum		

Comments: chr

Inspection Comments:

Has this Vehicle been restricted? No Yes

Name of the person who did the road test:

Inspector Name: CRAWFORD, TREVOR STEVEN

Signature:

This Inspection Report was submitted to CVSE on 2023-Feb-10 11:12 AM

The Inspector's signature above is certification that the vehicle has been inspected in the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 219 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing the vehicle inspection and for generally administering the vehicle inspection program and the National Safety Code (e.g. regulatory services, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the St. Manager, NRC/CP of the Commercial Vehicle Safety Enforcement.

CVSE014

2/10/2023 1:12:00 PM