



BRITISH COLUMBIA

# Commercial Vehicle Inspection Report

Decal Number: GK59732  
Decal Expiry Date: 2026-Sep-30  
Inspection Number: 21483890

B06-2

Inspection Result:  
**PASS**

FACILITY: MODERN DIESEL TRUCK REPAIR LTD. / S15400  
INSPECTOR: DHALMAL, HARPINDER SINGH / 300434  
WORK ORDER #:

INSP. TYPE: Complete  
INSP. CLASS: Class 3 - Trailer and Semi-Trailer  
INSP. REASON: Annual

INSP. START: 2025-Sep-03 07:20 AM PDT  
INSP. COMPLETE: 2025-Sep-03 09:25 AM PDT

VEHICLE JUR: British Columbia  
PLATE #: 86421K  
SCENCED GVW(kg): 0  
VEHICLE YEAR: 2007  
MAKE: GREAT DANE  
MODEL:

REGI: 13881995  
UNIT/FLEET#: TL160  
BODY STYLE: Van Trailer  
ODOMETER:  
HUB ODOMETER:  
BRAKE TYPE: Air  
FUEL TYPE:

VIN: 1GRAA06277B704811  
OWNER/LESSEE NAME: TRANSTAR LOGISTICS, LTD.  
ADDRESS: 104-7728 128 ST, 104-7728 128 ST  
Surrey, British Columbia  
V3W1L3, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) AXLE 1, 2 RIGHT SIDE SLACK ADJUSTER REPLACED
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

**Brake Chamber Type, Size and Push Rod Stroke (mm)**

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	35	35
2	Clamp	30	Automatic	35	35

Comment:

**Tire Tread Depth (mm)**

Outer L	Inner L	Inner R	Outer R	Steering
9	9	9	9	
10	10	10	10	

Comment:

**Brake Camshaft Rotation (degrees)**

Axles	Left	Right
1	65	70
2	65	65

Comment:

**Brake Lining/Pad (mm)**

Lining/Pad	Left	Right
Lining (Shoe)	16	17
Lining (Shoe)	16	16

Comment:

**Rotor Thickness or Drum Inside Diameter (mm)**

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:  
 Has this Vehicle been road tested?  No  Yes  
 Inspector: DHALMAL, HARPINDER SINGH  
 Signature:   
 Road Tester:

This Inspection Report was submitted to CVSE on 2025-Sep-03 03:29 PM PDT  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.  
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCA/IP at the Commercial Vehicle Safety Enforcement  
 CVSE0014  
 2025 9 29 56 PM PDT