



Commercial Vehicle Inspection Report

Decal Number: RD06573
Decal Expiry Date: 2025-Oct-07
Inspection Number: 21510008

Inspection Result:

FAIL

FACILITY:	TRIDEM SERVICES LTD / S4621	INSP. TYPE:	Complete	INSP. START:	2025-Sep-23 08:00 AM PDT
INSPECTOR:	ASSELS, HENRY KEITH / 200939	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2025-Sep-23 11:15 AM PDT
WORK ORDER #:	48283	INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	02412102	VIN:	2P9BL3DN84A015918
PLATE #:	03104J	UNIT/FLEET#:	133	OWNER/LESSEE NAME:	Nortrans, Freight Management LTD.
LICENCED GVW(kg):	999999	BODY STYLE:	Flat Deck Trailer	ADDRESS:	#7-215 Neave Rd, #7-215 Neave Rd
VEHICLE YEAR:	2004	ODOMETER:			Kelowna, British Columbia
MAKE:	MAGNUM	HUB ODOMETER:			V1V2L9, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Failed	#1 R/H & #3 R/H TRAILING ARMS CRACKED. #1R & #3L AIR BAGS LEAKING.
Section 3 - Brake System	Failed	#2 AXLE R BRAKE SHOES SEPARATING. ALL BRAKE HAVE HIGH CAM ROTATIONS.
Section 3A - Air Brakes	Failed	#2 R HALDEX PIN & BUSHING WORN.
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Not Applicable	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Failed	CRACKS & ROTTED CROSSMEMBERS. CRACK @ GUSSETT ABOVE #3 AXLE. CRACKS @ CROSSMEMBER ABOVE #1 AXLE
Section 9A - Tires	Failed	#3 L TIRE 4/32 TREAD
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	40	40	7.9	8.7	12.7	12.7	
2	Clamp	30	Automatic	40	40	10.3	8.7	11.9	11.9	
3	Clamp	30	Automatic	40	40	3.2	5.6	6.4	7.9	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	118	106
2	103	116
3	110	113

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	12	12
Lining (Shoe)	14	12
Lining (Shoe)	10	9

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	0.00	0.00
Drum	0.00	0.00
Drum	0.00	0.00

Comment:

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date:  Road Tester:
Inspector: ASSELS, HENRY KEITH Signature:

This Inspection Report was submitted to CVSE on 2025-Sep-25 02:11 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

9/25/2025 2:11:28 PM PDT