

03781616

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba
A771818

Date Inspection Started: 05/10/23
Date Inspection Completed: 13/10/23
Inspection Expiry Date: 31/10/24

Station Number: 161143
Mechanic Number: 10267
Vehicle Owner: 32 RAVENHILL ROAD
Address: 32 RAVENHILL ROAD
City: WILKINSON
Province: MB
Postal Code: R3K5
Phone: 431-910-0009

Station Name: KGS Truck & Trailer
Mechanic Signature: [Signature]
Vehicle Identification Number: 527SR5335FM004203
Make: GMC
Model: Refer
Year: 15
Unit #: R303

Pass/Safe Vehicle ☒
Fail/Unsafe Vehicle ☐
Fail/Hazardous ☐

Licence Number: T811842
Prov.: MB
NS #: [Blank]
Odometer Reading: [Blank]
Odom. Type: ☐ km ☐ mi

Confirmed legible Vehicle Identification Number on vehicle ☒

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X	X	Section 6 - Lamps: Defects (if any) 1 (H) Right Side Marker Light off W 1 (I) Clearance Light off W
X		Section 7 - Electrical System: Defects (if any)
X	X	Section 8 - Body: Defects (if any) 2 (H) Right Side Door Hinge Broken
X	X	Section 9 - Tire & Wheel: Defects (if any) 4 (H) Thrust Unkwn
X		Section 10 - Coupling Devices: Defects (if any)

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	11/16	11/16	1.600	1.622		
2	11/16	5/8	1.561	1.591		
3	5/8	5/8	1.590	1.589		
4						
5						
Final Measurement						

Axle	Initial		Corrected	
	L	R	L	R
1	9	9	8	8
2	8	8	10	6
3	6	8	5	9
4				
5				

Axle	Initial		Corrected	
	L	R	L	R
1	100	100	100	80
2	100	100	90	100
3	100	100	100	100
4				
5				

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: All wheel bearings after 10 km

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: [Signature] Date: 13/10/23

