



Commercial Vehicle Inspection Report

Decal Number: GJ63925
Decal Expiry Date: 2026-May-31
Inspection Number: 21359734

Inspection Result:

PASS

FACILITY: JUST DIESEL / S7036 INSP. TYPE: Complete INSP. START: 2025-May-17 06:00 PM PDT
INSPECTOR: FREIMULLER, CURTIS E WALTER / 114909 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2025-May-22 07:45 AM PDT
WORK ORDER #:

VEHICLE JUR: British Columbia REGI: 04570540 VIN: 2L9ESCE32V1078306
PLATE #: 17322K UNIT/FLEET#: TS01 OWNER/LESSEE NAME: THARROW CRANE LTD.,
LICENCED GVW(kg): 999999 BODY STYLE: Lowbed Trailer ADDRESS: PO BOX 1501 STN A
VEHICLE YEAR: 1997 ODOMETER: Prince George, British Columbia
MAKE: ARROW HUB ODOMETER: V2L4V5, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) REPLACE RH#3 SHOCK
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACE #3 AXLE BRAKES AND LH WHEEL SEAL, SECURE LOOSE LINES
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) REPAIR LIGHTS AS NEEDED
Section 7 - Electrical System	Repaired (same day) SECURE LOOSE WIRING
Section 8 - Frame and Body	Repaired (same day)
Section 9A - Tires	Repaired (same day) REPLACE TIRES AS NEEDED
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	38	38	11	8	10	9	
2	Clamp	30	Automatic	38	38	13	9	10	12	
3	Clamp	30	Automatic	38	38	10	11	13	13	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	85	82	Lining (Shoe)	13	14	Drum		
2	60	75	Lining (Shoe)	16	13	Drum		
3	30	30	Lining (Shoe)	20	20	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:
Has this Vehicle been road tested? No Road Test Date:
Inspector: FREIMULLER, CURTIS E WALTER Signature: Road Tester:

This Inspection Report was submitted to CVSE on 2025-May-22 10:32 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

5/22/2025 10:32:43 AM PDT