



**BRITISH
COLUMBIA**

Commercial Vehicle Inspection Report

Decal Number: GK70835
Decal Expiry Date: 2026-Aug-31
Inspection Number: 21479143

103

Inspection Result:

PASS

B10-2

FACILITY:	BRIGHT QUALITY ENTERPRISES LTD / S15780	INSP. TYPE:	Complete	INSP. START:	2025-Aug-29 08:00 AM PDT
INSPECTOR:	KAILA, JOBAN SINGH / 202325	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 6601 kg or more	INSP. COMPLETE:	2025-Aug-29 09:00 AM PDT
WORK ORDER #:		INSP. REASON:	Annual		

VEHICLE JUR:	British Columbia	REGI:	01357388	VIN:	1FLW6HCB8SL682081
PLATE #:	VG0482	UNIT/FLEETS:		OWNER/LESSEE NAME:	G LINE TRUCKING LTD.
LICENCED GVW(kg):	30000	BODY STYLE:	Truck Tractor	ADDRESS:	52889 STONEWOOD LTD
VEHICLE YEAR:	1995	ODOMETER:	464247 KM		Rosedale, British Columbia
MAKE:	FREIGHTLIN	HUB ODOMETER:			V0X1X1, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) tie up rear rubbing hoses
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) steering coil top up and hose clamp tighten
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) dr fix
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 8A - Tires	Passed
Section 8B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axes	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	32	33	8			8	✓
2	Clamp	30	Automatic	35	35	12	11	12	12	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axes	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	75	80	Lining (Shoe)	14	14	Drum		
2	50	55	Lining (Shoe)	17	18	Drum		
Comment:			Comment:		Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.			

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: KAILA, JOBAN SINGH
Road Test Date: 
Signature: _____
Road Tester: _____

This Inspection Report was submitted to CVSE on 2025-Aug-29 04:40 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 218 of the Motor Vehicle Act and Division 23 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement.

CV/SE014
8/29/2025 4:40:20 PM PDT