



Commercial Vehicle Inspection Report

Decal Number: **GJ95302**
Decal Expiry Date: **2026-Jun-30**
Inspection Number: **21382946**

B13-1

Inspection Result:
PASS

FACILITY: ALBION TRUCK REPAIRS LTD. / S6995 INSP. TYPE: Complete INSP. START: 2025-Jun-08 08:15 AM PDT
INSPECTOR: HUANG, BOWEN / 112918 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2025-Jun-08 08:35 AM PDT
WORK ORDER #:

VEHICLE JUR: British Columbia REGI: 13546482 VIN: 1UYFS2459NA722205
PLATE #: 07314K UNIT/FLEET#: OWNER/LESSEE NAME: WATSON, ROSS
LICENCED GVW(kg): 0 BODY STYLE: Lowbed Trailer ADDRESS: 9955 ODEL ST, 9955 ODEL ST
VEHICLE YEAR: 1992 ODOMETER: Maple Ridge, British Columbia
MAKE: UTILITY HUB ODOMETER: V2W1V9, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	25	25	10	10	10	10	
2	Clamp	30	Automatic	25	25	14	14	14	14	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad		Left	Right	Rotor/Drum	Left	Right
1	30	30	Lining (Shoe)		20	20	Drum		
2	30	30	Lining (Shoe)		20	20	Drum		

Inspection Comments:
Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: HUANG, BOWEN Signature: Bowen Huang

This Inspection Report was submitted to CVSE on 2025-Jun-08 10:22 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.