



Inland Truck & Equipment
 816 Industrial Rd No. 1
 Cranbrook, BC V1C 4C6
 inland-group.com

VEHICLE INSPECTION REPORT

DATE: Aug 7/24	MECHANIC:	CUSTOMER: Lance Fiddler
VEHICLE #: 19523	MILEAGE: 1	RO#: 18585

		REPAIR	REPLACE	CAUTION
1	Front Right Fender falling off	✓		
2	Front L & R markers not working	✓		
3	RH Rear inner tire flat	✓		
4	LH Rear outer tire flat	✓		
5	LH #2 Axle outer tire flat	✓		
6	LH Rear Hub is out of oil	✓		
7	LH center mud flap ripped		✓	
8	LH Rear tires need to be replaced		✓	
9	Chain for box inop and broken	✓		
10	RH Rear Lights bent	✓		
11	Missing Rear Upper Clearance Lights			
12	Vin tag hard to read. re stamp vin	✓	✓	
13	RH Rear Mud Flap Ripped			
14				
15				
16				
17				
18				
19				
20				
21				

BRAKES				L.H.					R.H.				
AXLE	TYPE	SIZE	SLACK	TRAVEL	ROTATION	LINING	Outside tire	Inside tire	TRAVEL	ROTATION	LINING	Inside tire	Outside tire
1	C	30	A/M	1.5	40	16	18	18	1.5	45	15	18	15
2	C	30	A/M	1.5	75	8	18	18	1.5	60	8	15	15
3	C	30	A/M	1.5	60	10	15	5	1.5	75	8	3	3
4			A/M										
5			A/M										

Repaired to Pass CUP